#### South Coast On-Road Heavy-Duty Vehicle Incentive Measure 2019 Progress Report Appendix B

**Example District Inspection Report** 

## On Road Replacement –Pre Inspection

Truck # 27 3-24-19








Right Side View

Front View









Rear View


## On Road Replacement –Pre Inspection Truck # 27




## On Road Replacement –Pre Inspection Truck # 27 3-24-19


8.25 VEHICLE SAFETY STANDARDS IN EFFECT ON THE DATE VEHICLE IDENTIFICATION NUMBER 1M1AW02Y1AN009641 8.25 RIMS AT 0 AT 0 , AT 758 , AT 758 AT 758 KPA ( KPA KPA ( 110 KPA ( 110 KPA ( 110 PSI) COLD DUAL PSI) COLD PSI) COLD DUAL PSI) COLD SINGLE PSI) COLD 4MR3306








### On Road Replacement –Pre Inspection Truck # 27 3-24-19




Right side



**Left Side** 


# On-Road Replacement - Pre-Dismantle Inspection

Mack CXU613 #27 August 28, 2019




**Emissions Tag** 

**Engine Serial No.** 




k now and press

Odometer




Engine Left Side View







## On-Road Replacement – Destruction Mack CXU613 Truck #27 October 12, 2019




**Equipment View** 



Front



Left




Right

≦


Back

## On-Road Replacement – Destruction Mack CXU613 Truck #27 October 12, 2019



**Emissions Tag** 

**Engine Serial No.** 



**Engine View** 




**Engine block hole** 


Frame Cut

## On-Road Replacement – Post-Inspection Mack AN64TE Truck #101


June 29, 2019




**Equipment View** 



Front



Left



Back




Right

## On-Road Replacement – Post-Inspection Mack AN64TE Truck #101 June 29, 2019

CID/L 729/11.9	Spars, Flug sap (in), U14 CPL 48.75 Date of Mig. 12/18	Model ISXI2N 400 Idle Speed 700-900	ESN 75080613
VENEGATED ASSENDED.	WARNING, Injury may result and a exceed published maximum values	E.C.S. Code HOZSPCM,T Valve Lash (in/mm) .018/	Adv. HP 400
Cummind Inc. 5484380 Assembled in the U.S.A. ®	iorranty is vaided if fuel rate, RPU, or I for this model and application	4 WC /457 Int. 036/914	at 1800
2208.1, opd snay be adject parament to Collection Code	oto o primory attendant servi deset engine. Inis origine i allharket empine has received corollicat Resources Based because it i pursuant to Coffernia Code	Extr. Fig.   Extr.   Cas	RPM NOX
		This copies continues to U.S. (F), and Collisions or publicate of the Collision of the Coll	


**Emissions Tag** 

**Engine Serial No.** 



**Engine Left Side View** 

**Engine Right Side View** 



Odometer