MODIFICATION HIGHLIGHTS for Executive Orders VR-202-AH

Part I: Executive Order

Global Change

- Changed revision letter from AG to AH for **VR-202**

Legal Language

- Page 1
  Added "whereas" paragraph describing the nature of the amendment request from Veeder-Root., to update the ISD software, version 1.08, to the recently amended sections 9.2.4 and 9.3.3 of CP-201 for Veeder-Root's TLS 450Plus console.
- Added "It is further ordered" paragraph describing the removal of INCON ISD components for new installations.

Exhibit 1: Equipment List
NOTE: Restructured and figure numbers renumbered

- Page 12
  Added Figure 1-1 – Image of Hanging Hardware Assembly
- Inverted Coaxial Hose
  Figure 1-5a => Figure 1-3.1; Figure 1-5b => Figure 1-3.2; Figure 1-5c => Figure 1-3.3; Figure 15-5d => Figure 1-3.4
- Breakaway Coupling / Swivel
  Figure 1-10a => Figure 1-4.1; Figure 1-10b => Figure 1-4.2; Figure 1-10c => Figure 1-4.3; Figure 1-10d => Figure 1-4.4; Figure 1-10e => Figure 1-4.5; Figure 1-20 => Figure 1-4.6; Figure 1-21 => Figure 1-4.8; Figure 1-22 => Figure 1-4.9; Figure 1-23 => Figure 1-5
- Flow Limiter
  Figure 1-11 => Figure 1-6.1; Figure 1-12 => Figure 1-6.2; Figure 1-13 => Figure 1-6.3; Figure 1-14 => Figure 1-6.4
- Breakaway and Flow Meter options
  Figure 1-6 => Figure 1-7; Figure 1-7 => Figure 1-8
- Dispensers Conversion Adapter
  Figure 1-8 => Figure 1-9
- Vacuum Pump /Module
  Figure 1-15 => Figure 1-10; Figure 1-16 => Figure 1-11
- Processor
  Figure 1-3 => Figure 1-12; Figure 1-4 => Figure 1-13; Figure 1-19 => Figure 1-14

- LCT
  Figure 1A-LCT-1 => Figure 1-15; Figure 1A-LCT-2 => Figure 1-15
- Maintenance Tracker
  Figure 1-17 => Figure 1-16
- Reorganized the ISD equipment list. Created a separate equipment list for the TLS-350 Series console, and a separate equipment list for the TLS-450PLUS console. Separated the equipment list for the Veeder--Root- wireless components.
  Figure 1-ISD-VR-10 => Figure 1-ISD-VR-5, Figure 1-ISD-VR-11 =>
  Figure 1-ISD-VR-6
- Added Footnote 31
  *"ISD software version 1.08 is compatible **only** with Veeder-Root TLS-450Plus and both processors, ARID Permeator AT-150 and Clean Air Separator."*
- Remove following note from Footnote 38
  "Software Version 1.07 must be installed at new GDFs or those undergoing a major modification as determined by date when the district issues the permit to construct."
- Added Software Version1.08 to Table 1-ISD-1,Veeder-Root ISD Software Version Compatibility Matrix"
- Added footnote 39, with following:
  "ISD Software version 1.08 is only compatible with the Veeder-Root TLS-450PLUS system."
- Veeder-Root ISD figure number changed
  Figure 1-ISD-VR-6 => Figure 1-ISD-VR-1.2, Figure 1-ISD-VR-7 =>
  Figure 1-ISD-VR-1.3; Figure 1-ISD-VR-9 => Figure 1-ISD-VR-1.1; Figure 1-ISD-VR-8 => Figure 1-ISD-VR-2.2; Figure 1-ISD-VR-12 => Figure 1-ISD-VR-2.3;
  Figure 1-ISD-VR-3 => Figure 1-ISD-VR-2.1; Figure 1-ISD-VR-5 => Figure 1-ISD-VR-3
- Update the component description and Model number to Equipment List for Wireless Component

Component	Manufacturer/Model
TLS-RF Wireless 2 Console	Veeder-Root ~~332242-002~~0330020-668
RF Wireless 2 Transmitter-Kit	Veeder-Root ~~332235-016~~0330020-674
RF Wireless 2 Battery Pack	Veeder-Root ~~332425-011~~0330020-718
RF Wireless 2 Repeater	Veeder-Root ~~332440-030~~0330020-670
RF Wireless 2 Receiver	Veeder-Root ~~332440-029~~0330020-669

Exhibit 2: Equipment List

- Page 4
- Item 5, Rewritten to incorporate TLS-450PLUS as following:
  "The Permeator AT-150 can be operated on GDF installations that have one of the following ISD installations:
    - *Veeder-Root TLS-350 Series with ISD software version 1.06 or later;*
    - *Veeder-Root TLS-450PLUS with ISD software version 1.06 or later."*
- Table 2-1
  - Update Table with a new row to add Version 1.08 and two table notes to clarify the compatibility of the ISD software version

Assist VR-202 Series	Version 1.07**	N/A	Required for new installations and major modifications
	Version 1.08***	N/A	Required for new installations and major modifications

** Version 1.07 is compatible with the Veeder-Root TLS-350 and TLS-450PLUS systems.
*** Version 1.08 is only compatible with the Veeder-Root TLS-450PLUS system. The Veeder-Root TLS-350 is only compatible with ISD versions 1.07 or earlier.

Exhibit 3 to Exhibit 15

- NO CONTENT CHANGE

Part II: CARB Approved Installation, Operation, and Maintenance Manual (IOM)

Global Change:

- Changed revision letter from AG to AH for **VR-202**

IOM Table of Contents

- NO CHANGE

IOM 1 – 9,11-15

- NO CHANGE

IOM 10

- Replaced Veeder Root Manual No: 577014-461 Rev C with Rev D
- Addition of the Containment Monitoring reports
    - Page 64
    - Page 65
    - Page 66
    - Page 67
- Added new RS-232 command
    - Page 75
- Sample of Pressure Ullage report
    - Page 77