MODIFICATION HIGHLIGHTS
for
Executive Orders VR-203-AF

Part I: Executive Order

Global Change

- Changed revision letter from AE to AF for **VR-203**

Legal Language

- Page1 - Added "whereas" paragraph describing the nature of the amendment request from Husky Corporation requested to include two breakaways to the list of hanging hardware.

Exhibit 1: Equipment List

- Page 2
  - Added 3360VR (reconnectable) and 5900 (non-reconnectable) to Component section of the breakaway coupling.
- Page 3
  - Table 1-1 titled "Allowable Hanging Hardware Combinations with Corresponding Processor "
    - Added new column titled Husky for Breakways
- Page 10
  - Update the component description and Model number to Equipment List for Wireless Component

Component	Manufacturer/Model
TLS-RF Wireless 2 Console	Veeder-Root ~~332242-002~~0330020-668
RF Wireless 2 Transmitter-Kit	Veeder-Root ~~332235-016~~0330020-674
RF Wireless 2 Battery Pack	Veeder-Root ~~332425-011~~0330020-718
RF Wireless 2 Repeater	Veeder-Root ~~332440-030~~0330020-670
RF Wireless 2 Receiver	Veeder-Root ~~332440-029~~0330020-669

- Page 21
  - Added new page, and images of both Husky breakaways (with and without scuff guards) for identification purposes to Figure 1-5

Exhibit 2: System Specifications

- Updated items 1 and 2 to Breakaway Section as follows:
    1. "The VST breakaways, Model VSTA-EVR-SBK, the EMCO safe break couplings, Model A4119EVR, and the Husky breakaway, Model 5900, are non-reconnecting and shall be replaced following a drive off.
    2. The EMCO safe break couplings, Model A4119EVR (Reconnectable), and Husky breakaway, Model 3360VR (reconnectable), can be reconnected following a drive-off after conducting a visual and functional assessment per the drive-off procedure."

Exhibit 3: Manufacturing Performance Specifications and Warranties

- Page 1
    - Updated CP-201 amend date (April 23, 2015 to July 12, 2023)
- Page 21
    - Added Warranty information for Husky Corp

Exhibit 4 to Exhibit 21

- NO CONTENT CHANGE

Part II: CARB Approved Installation, Operation, and Maintenance Manual (IOM)

Global Change:

- Changed revision letter from AE to AF for **VR-203**

IOM Table of Contents

- NO CHANGE

IOM 1 – 4,6-8,10-21

- NO CHANGE

IOM 5:

Page 3; added Husky under Test Procedure

IOM 9

Added installation manual for Husky Safe-T-Break®