MODIFICATION HIGHLIGHTS
for
Executive Orders VR-204-AF

Part I: Executive Order

Global Change

- changed revision letter from AE to AF for **VR-204**

Legal Language

- Page 1 - Added "whereas" paragraph describing the nature of the amendment request from Veeder Root., to update the ISD software, version 1.08, to the recently amended sections 9.2.4 and 9.3.3 of CP-201 for Veeder-Root's TLS-450Plus console.
- Page1 - Added "whereas" paragraph describing the nature of the amendment request from Husky Corporation requested to include two breakaways to the list of hanging hardware.
- Added "It is further ordered" paragraph describing the removal of INCON ISD components for new installations.

Exhibit 1: Equipment List

- Page 2
  - Added 3360VR (reconnectable) and 5900 (non-reconnectable) to Component section of the breakaway coupling.
- Page 3
  - Split the Table 1-1 into two tables
    - Table 1-1 titled "Allowable Hanging Hardware Combinations with Corresponding Processor "
      - Added new column titled Husky for Breakaways
    - Table 1-2 titled "Allowable ISD system with Corresponding Processor "
- Page 11
  - Update the component description and Model number to Equipment List for Wireless Component

Component	Manufacturer/Model
TLS-RF Wireless 2 Console	Veeder-Root ~~332242-002~~0330020-668
RF Wireless 2 Transmitter-Kit	Veeder-Root ~~332235-016~~0330020-674
RF Wireless 2 Battery Pack	Veeder-Root ~~332425-011~~0330020-718
RF Wireless 2 Repeater	Veeder-Root ~~332440-030~~0330020-670
RF Wireless 2 Receiver	Veeder-Root ~~332440-029~~0330020-669

- Page 13
  - Added Software Version1.08 to Table 1-3, "Veeder-Root ISD Software Version Compatibility Matrix"
- Added footnote 24, with following:
  "ISD Software version 1.08 is only compatible with the Veeder- Root TLS-450PLUS system."
  - All foot notes after will increase by 1 value
- Page 24
  - Added new page, and images of both Husky breakaways (with and without scuff guards) for identification purposes to Figure 1-5

Exhibit 2: System Specifications

- Updated items 1 and 2 to Breakaway Section as follows:
  1. "The VST breakaways, Model VSTA-EVR-SBK, the EMCO safe break couplings, Model A4119EVR, and the Husky breakaway, Model 5900, are non-reconnecting and shall be replaced following a drive off.
  2. The EMCO safe break couplings, Model A4119EVR (Reconnectable), and Husky breakaway, Model 3360VR (reconnectable), can be reconnected following a drive-off after conducting a visual and functional assessment per the drive-off procedure."

Exhibit 3: Manufacturing Performance Specifications and Warranties

- Page 1
  - Updated CP-201 amend date (April 23, 2015 to July 12, 2023)
- Page 21
  - Added Warranty information for Husky Corp

Exhibit 4 to Exhibit 21

- NO CONTENT CHANGE

Part II: CARB Approved Installation, Operation, and Maintenance Manual (IOM)

Global Change:

- Changed revision letter from AE to AF for **VR-204**

IOM Table of Contents

- NO CHANGE

IOM 1 - 3

- NO CHANGE

IOM 4

- Added Foot note to page 1 for Table 1 and 7
  - "[3] Applicable only to ISD software versions earlier than 1.08."
- Added EndNote to Tables 2,3, and 4 for pressure alarms
  - "[3] Applicable only to Veeder Root ISD software versions earlier than 1.08. In version 1.08, the ISD software no longer includes any pressure alarms (Gross and Degradation)."

IOM 5 – 12a

- NO CHANGE

IOM 12b

- Replaced Veeder Root Manual No: 577014-484 Rev C with Rev D
  - addition of the Containment Monitoring reports
    - Page 69 – Example of CARB Monthly Report
    - Page 70 – Example of Daily Collection Report
    - Page 71 - Example of Daily Containment Report
    - Page 72 – Example of Monthly Status Event Report
  - Added new RS-232 command
    - Page 80

IOM 13 – 27

- NO CHANGE