

Department of Conservation, Geologic Energy Management Division
Doug Ito
STATE OIL AND GAS SUPERVISOR
715 P Street, MS 19-06 (Legal Office)
Sacramento, California 95814
Telephone (916) 323-6733

STATE OF CALIFORNIA
NATURAL RESOURCES AGENCY
DEPARTMENT OF CONSERVATION
GEOLOGIC ENERGY MANAGEMENT DIVISION

ORDER TO PAY A CIVIL PENALTY AND PERFORM REMEDIAL WORK
NO. 1656

Operator: Bridgeland Resources, LLC (11583)
Field Names: Santa Fe Springs, Rosecrans
County: Los Angeles

I. Introduction

The State Oil and Gas Supervisor (**Supervisor**), acting through the Geologic Energy Management Division (**CalGEM**), and under the authority of Division 3 of the Public Resources Code (**PRC**; commencing with PRC section 3000) and title 14 of the California Code of Regulations (**Regulations**), may impose a civil penalty on a person who violates any statutory provision of the PRC, or any regulation that implements those statutory provisions. (PRC, § 3236.5.)

Based on CalGEM's records, Bridgeland Resources, LLC (**Operator**) is the "operator" (as defined in PRC, § 3009) and is responsible for the Wells and associated Production Facilities identified on **Attachment A**, incorporated herein (the "**Wells**" and "**Facilities**"). As described in more detail below, Operator has not maintained compliance with applicable requirements for operation of the Wells and the Facilities. Operator's failure to comply with the Regulations poses a potential threat to life, health, property, and natural resources and constitute violations requiring remedial work and for which the Supervisor has determined imposition of a civil penalty is appropriate. Therefore, pursuant to PRC sections 3013, 3106, 3224, 3225, 3226, 3236.5, and 3270 and Regulations sections 1777 and 1722 subdivision (a), the Supervisor is ordering Operator to (1) perform remedial work to bring the Wells and Facilities into compliance and (2) pay an administrative civil penalty for the violations.

Attachment B, incorporated herein, contains a list of definitions and authorities that are applicable to this Order.

II. Alleged Acts and Omissions

Based on CalGEM's records, at all times relevant to this Order, Operator was the operator, as defined in PRC section 3009, of the Wells and Facilities. On or about May 15, 2025, May 16, 2025, May 19, 2025, June 11, 2025, June 16, 2025, June 18, 2025, June 25, 2025, June 26, 2025, September 12, 2025, September 18, 2025, October 9, 2025, and December 15, 2025, CalGEM conducted inspections of the Wells and Facilities where the violations described below were observed and documented in the Santa Fe Springs and Rosecrans Fields. (**Attachments C, D, E, F, G, H, I, J, K, L, M, N, and O**, incorporated herein.)

CalGEM records reflect Operator has not maintained compliance with applicable requirements for operation of the Wells and the Facilities. Operator’s lack of adherence to the Regulations poses a potential threat to life, health, property, and natural resources. The violations at issue are identified below.

A. Failure to maintain production facilities in good condition and in a manner to prevent leakage or corrosion (Regulations, § 1777, subd. (a))

Operators are required to maintain production facilities in good condition and in a manner to prevent leakage or corrosion and to safeguard life, health, property, and natural resources and conduct operations in accordance with good oilfield practices. (Regulations, § 1777, subd. (a).) Production facilities include wellheads. (PRC, § 3010; Regulations, § 1760, subd. (r).)

During the inspection, CalGEM observed a liquid leak at the following wellhead and therefore not being maintained in a good condition and in a manner to prevent leakage or corrosion, in violation of the Regulations, section 1777, subdivision (a):

API	Well Designation	Violation Status
0403715947	051-B	Resolved

The violation of Well 051-B was remediated by Operator on or around September 11, 2025. During the inspection, CalGEM observed the following tank leaking in violation of Regulations section 1777, subdivision (a):

Facility Setting ID	Facility Setting Name	Facility (Component) ID	Facility (Component) Name	Facility (Component) Type	Violation Status
90295464	Main Tank Farm	13440	Divert 2	Tank	Active

As of the date of this Order, CalGEM does not have any records from Operator demonstrating that the violation has been corrected.

///

///

B. Failure to Keep Well Cellar Drained (Regulations, § 1777, subd. (c)(3))

The well cellar is an excavated area around the wellhead that provides space for equipment at the top of the wellbore. Operators are required to keep well cellars drained. (Regulations, § 1777, subd. (c)(3).)

During the inspections, CalGEM observed fluids in the well cellar, in violation of Regulations, section 1777, subd. (c)(3), at the following Wells:

API	Well Designation	Violation Status
0403713643	Trust 1	Resolved
0403715688	831-E	Resolved
0403715723	Santa Fe 519-E	Resolved
0403716267	Santa Fe 717-P	Resolved
0403715696	W-638-N	Resolved
0403715797	Anderson 538-P	Resolved
0403715968	637-E	Resolved
0403715712	Anderson W-530-G	Resolved
0403709042	Bell 446-B	Resolved
0403709063	Bell 439-F	Resolved
0403727440	Bell 584	Resolved
0403709071	Bell 440-L	Resolved
0403730067	Bell 200-02	Resolved
0403714772	Bell 466-C	Resolved
0403709068	Bell W445F	Resolved
0403723601	Bell 498-C	Resolved
0403709036	Bell 434-F	Resolved
0403714759	Bell 444-B	Resolved
0403709066	Bell 427-C	Resolved
0403727368	Bell 650	Resolved
0403700102	Bell 429-E	Resolved
0403727214	Bell 583	Resolved
0403709040	Santa Fe Comm. 488-E	Resolved
0403714760	Bell W-433-C	Resolved
0403723455	Bell 496-B	Resolved

0403709070	Bell W-431-F	Resolved
0403727224	Bell 400-02	Resolved
0403714762	217-B	Resolved
0403727379	Bell 654	Resolved
0403723347	Bell 494-C	Resolved
0403700099	Bell 421-N	Resolved
0403715947	051-B	Resolved
0403714778	410-C	Resolved
0403714770	W-200-C	Resolved
0403714761	W-401-C	Resolved
0403709048	409-C	Resolved
0403714753	415-E	Resolved
0403709069	414-C	Resolved
0403714754	W-413-E	Resolved
0403715983	Anderson 557-C	Resolved
0403714667	Rosecrans 16	Resolved
0403714451	Rosecrans 1	Active
0403714452	Rosecrans 2	Active
0403714666	Rosecrans 11	Resolved
0403713642	Rosecrans 47	Resolved
0403723668	Trust 19W	Resolved
0403714446	O'Dea 18	Active
0403714668	Rosecrans 17	Resolved
0403723667	O'Dea 26W	Resolved
0403714999	Rosecrans 8	Active
0403715014	Rosecrans 35	Active
0403714674	Rosecrans 28	Active
0403714431	O'Dea 2	Active
0403715020	Rosecrans 41	Active
0403715015	Rosecrans 36	Active
0403714656	Rosecrans A 5-A	Active
0403715021	Rosecrans 42	Active
0403714591	Wolfe 1	Active

0403715012	Rosecrans 32	Active
0403713647	Trust 5	Active
0403714568	Riverside 1	Active
0403714474	Callender 1	Active
0403716029	Santa Fe 768-B	Active
0403716722	819-C	Active
0403716222	Off 773-M	Active

Over forty violations were remediated by Operator between September 11, 2025 and July 7, 2026. As of the date of this Order, CalGEM does not have any records from Operator demonstrating that the remaining violations were corrected.

Civil Penalty

Based on the foregoing Alleged Acts and Omissions and pursuant to PRC section 3236.5, by this Order the Supervisor imposes on Operator an administrative civil penalty totaling forty thousand four hundred dollars (\$40,400.00) for the sixty-seven violations.

Violation Description	Number of Violations	Associated Civil Penalty per Violation	Civil Penalty Totals
Failure to Maintain Production Facilities in Good Condition and in a Manner to Prevent Leakage or Corrosion; Leaking Wellheads (Regulations, § 1777, subd. (a)) API 0403715947	1	\$1,000	\$1,000
Failure to Maintain Tank in Good Condition and in a Manner to Prevent Leakage or Corrosion; Leaking Tank (Regulations, § 1777, subd. (a)) Facility ID13340	1	\$500	\$500
Failure to Keep Well Cellar Drained (Regulations, § 1777, subd. (c)(3)) API 0403715688 API 0403713647 API 0403714568 API 0403714474	4	\$200	\$800

1	Failure to Keep Well Cellar Drained (Regulations, § 1777, subd. (c)(3))			
2	API 0403715723			
3	API 0403723455	5	\$300	\$1,500
4	API 0403714452			
5	API 0403723668			
6	API 0403714667			
7	Failure to Keep Well Cellar Drained (Regulations, § 1777, subd. (c)(3))			
8	API 0403716029			
9	API 0403709042			
10	API 0403709063			
11	API 0403727440			
12	API 0403709036	13	\$400	\$5,200
13	API 0403709040			
14	API 0403714760			
15	API 0403709070			
16	API 0403714668			
17	API 0403723667			
18	API 0403714999			
19	API 0403714431			
20	API 0403715021			
21	Failure to Keep Well Cellar Drained (Regulations, § 1777, subd. (c)(3))			
22	API 0403716722	2	\$500	\$1,000
23	API 0403716222			
24	Failure to Keep Well Cellar Drained (Regulations, § 1777, subd. (c)(3))			
25	API 0403709071			
26	API 0403714772			
27	API 0403709068			
28	API 0403723601			
29	API 0403714759			
30	API 0403700102			
31	API 0403723347			
32	API 0403700099	16	\$600	\$9,600
33	API 0403714770			
34	API 0403714666			
35	API 0403714674			
36	API 0403714656			
37	API 0403713643			
38	API 0403714591			
39	API 0403715012			
40	API 0403713642			

1	Failure to Keep Well Cellar Drained (Regulations, § 1777, subd. (c)(3)) API 0403727224 API 0403709066	2	\$700	\$1,400
2				
3	Failure to Keep Well Cellar Drained (Regulations, § 1777, subd. (c)(3)) API 0403715696 API 0403715797 API 0403730067 API 0403714762 API 0403727379 API 0403709048 API 0403709069 API 0403714754 API 0403714451 API 0403714446 API 0403715014 API 0403715020 API 0403715983	13	\$800	\$10,400
4				
5				
6				
7				
8				
9				
10				
11				
12	Failure to Keep Well Cellar Drained (Regulations, § 1777, subd. (c)(3)) API 0403716267 API 0403715968 API 0403715712 API 0403727368 API 0403727214 API 0403715947 API 0403714778 API 0403714761 API 0403714753 API 0403715015	10	\$900	\$9,000
13				
14				
15				
16				
17				
18				
19			Total Civil Penalty:	\$40,400

For purposes of this Order, the Supervisor considered relevant circumstances when establishing the amount of the administrative civil penalty, including characterizing the violations as “minor” (as defined in PRC section 3236.5, subdivision (b)), the eight factors identified in PRC section 3236.5, subdivision (a), and the following: whether the Wells and tank are located in an urban area, as defined by Regulations section 1760, subdivision (y); are within a health protection zone, as defined by Regulations section 1765.1, subdivision (b); are environmentally sensitive, as defined by Regulations section 1760, subdivision (f); and whether the Wells are critical wells, as defined by Regulations section 1720, subdivision (a).

III. Operator's Required Actions

For the reasons stated herein, pursuant to PRC sections 3013, 3106, 3224, 3225, 3226, and 3236.5, and Regulations sections 1777 and 1722, **IT IS HEREBY ORDERED** that within 30 days, Operator:

- 1) Pay an administrative civil penalty of forty thousand four hundred dollars (\$40,400.00);

To remit payment of the civil penalty online, please visit <https://www.govone.com/PAYCAL/Home/SelectAgency> and select "California Department of Conservation Geologic Energy Management Division," then follow the instructions on the screen. When filling out the "order number" field, please type the order number followed by the letter "O."

To remit payment of the civil penalty by mail, please send a check payable to "Department of Conservation" to the following address:

Department of Conservation
CalGEM, Attn: Operational Management Unit
715 P Street, MS 1803
Sacramento, California 95814

Please include the Operator name, Order number, and phrase "Oil and Gas Environmental Remediation Account" on the check itself.

- 2) In accordance with PRC section 3224 and Regulations section 1777 Operator is required to:

- a. Stop all leaks from the following tank:

Facility Setting ID	Facility Setting Name	District	Facility (Component) ID	Facility (Component) Name	Facility (Component) Type
90295464	Main Tank Farm	Southern	13440	Divert 2	Tank

Note: Regulations section 1773.5, subdivision (b), prohibits Out-of-Service production facilities from being reactivated until all needed repairs have been completed and the production facility is in compliance with all applicable testing and inspection requirements. Operator is

required to submit required testing and inspection information to CalGEM for review prior to reactivation of the tanks pursuant to Regulations section 1773.4; and

b. Drain the well cellar, at the following Wells:

API	Well Designation
0403716222	Off 773-M
0403716029	Santa Fe 768-B
0403716722	Unnamed 819-C
0403714451	Rosecrans 1
0403714452	Rosecrans 2
0403714666	Rosecrans 11
0403713642	Rosecrans 47
0403723668	Trust 19W
0403714446	O'Dea 18
0403714668	Rosecrans 17
0403714667	Rosecrans 16
0403723667	O'Dea 26W
0403714999	Rosecrans 8
0403715014	Rosecrans 35
0403714674	Rosecrans 28
0403714431	O'Dea 2
0403715020	Rosecrans 41
0403715015	Rosecrans 36
0403714656	Rosecrans A 5-A
0403715021	Rosecrans 42
0403713647	Trust 5
0403714591	Wolfe 1

0403715012	Rosecrans 32
0403714568	Riverside 1
0403714474	Callender 1

Upon performing the required remedial work, please contact Renee Weigand at CalGEM's Southern District via email at Renee.Weigand@conservation.ca.gov.

IV. Operator's Appeal Rights

Operator may appeal this Order by filing a timely written notice of appeal with the Director as described in Article 6 (Appeals and Review) of Division 3 of the PRC, commencing with PRC section 3350. (PRC, § 3225, subd. (d).) If this Order is mailed to you, the Director must receive the appeal within fifteen (15) days from the date the Supervisor mails the Order. To file an appeal, a written notice of appeal may be sent via U.S. mail to:

Department of Conservation
Director's Office of Appeals
715 P Street, MS 19-06 (Legal Office, Chief Counsel)
Sacramento, California 95814

Or via electronic mail to: OfficeofAppeals@conservation.ca.gov.

If Operator files a timely written notice of appeal, Operator will be informed of the appeal hearing date, time, and place. Following the hearing, Operator will receive a written decision that affirms, sets aside, or modifies the appealed order.

If Operator does not file a timely written notice of appeal, or if the Order is affirmed following an appeal, this Order will become a final order and CalGEM may contract for performance of the work, pursuant to PRC section 3226, if, within 30 days of this Order, Operator has not, in good faith, commenced the work ordered. Any costs incurred by CalGEM to obtain compliance with this Order (which may include penalties and interest) will constitute a lien against Operator's real or personal property per PRC section 3423. (PRC, § 3356.)

V. Other Potential Actions to Enforce This Order

Failure to comply with Section IV (Operator's Required Actions) of this Order could subject Operator to further enforcement action. PRC section 3236 makes it a misdemeanor for

any person who violates, fails, neglects, or refuses to comply with any of the provisions of the oil and gas conservation laws commencing at PRC section 3000. PRC sections 3236.2 and 3236.3 authorize the Supervisor to seek for civil penalties and injunctive relief for failure to comply with an order or for violations of any provision in Chapter 1 of Division 3 of the PRC or any regulation that implements those statutes. PRC section 3236.5 authorizes the Supervisor to impose a civil penalty on a person who violates any provision in Chapter 1 of Division 3 of the PRC or any regulation that implements those statutes, and the Supervisor may in the future impose further civil penalties based on the facts and omissions underlying this order. PRC section 3237 authorizes the Supervisor to order the plugging and abandonment of a well or the decommissioning of a production facility if an operator has failed to comply with an order of the Supervisor within the time provided by the order or has failed to challenge the order on a timely basis. PRC section 3359 makes it a misdemeanor to fail or neglect to comply with an order of the Supervisor. Each day's further failure, refusal, or neglect is a separate and distinct offense. (PRC, § 3359.) By issuance of this Order, the Supervisor does not waive the right to take further enforcement actions.

DATED: 7/17/2026

Doug Ito

Doug Ito
State Oil and Gas Supervisor

Service List

Matt Sanders
Bridgeland Resources, LLC
12720 Telegraph Road
Santa Fe Springs, CA 90670

Via E-mail

msanders@bridgelandllc.com

Attachment A

(Wells and Production Facilities)

Operator Name: Bridgeland Resources, LLC**Operator Code:** 11583

API	Well Designation	Field Name	District
0403716222	Off 773-M	Santa Fe Springs	Southern
0403716029	Santa Fe 768-B	Santa Fe Springs	Southern
0403716722	unnamed 819-C	Santa Fe Springs	Southern
0403715723	Santa Fe 519-E	Santa Fe Springs	Southern
0403716267	Santa Fe 717-P	Santa Fe Springs	Southern
0403715688	unnamed 831-E	Santa Fe Springs	Southern
0403715696	unnamed W-638-N	Santa Fe Springs	Southern
0403715797	Anderson 538-P	Santa Fe Springs	Southern
0403709042	Bell 446-B	Santa Fe Springs	Southern
0403709063	Bell 439-F	Santa Fe Springs	Southern
0403715983	Anderson 557-C	Santa Fe Springs	Southern
0403715968	unnamed 637-E	Santa Fe Springs	Southern
0403715712	Anderson W-530-G	Santa Fe Springs	Southern
0403727440	Bell 584	Santa Fe Springs	Southern
0403709071	Bell 440-L	Santa Fe Springs	Southern
0403730067	Bell 200-02	Santa Fe Springs	Southern

0403714772	Bell 466-C	Santa Fe Springs	Southern
0403709068	Bell W445F	Santa Fe Springs	Southern
0403723601	Bell 498-C	Santa Fe Springs	Southern
0403709036	Bell 434-F	Santa Fe Springs	Southern
0403714759	Bell 444-B	Santa Fe Springs	Southern
0403709066	Bell 427-C	Santa Fe Springs	Southern
0403727368	Bell 650	Santa Fe Springs	Southern
0403700102	Bell 429-E	Santa Fe Springs	Southern
0403727214	Bell 583	Santa Fe Springs	Southern
0403709040	Santa Fe Comm. 488-E	Santa Fe Springs	Southern
0403715947	unnamed 051-B	Santa Fe Springs	Southern
0403714778	unnamed 410-C	Santa Fe Springs	Southern
0403715947	unnamed 051-B	Santa Fe Springs	Southern
0403714770	unnamed W-200-C	Santa Fe Springs	Southern
0403714761	unnamed W-401-C	Santa Fe Springs	Southern
0403709048	unnamed 409-C	Santa Fe Springs	Southern
0403714753	unnamed 415-E	Santa Fe Springs	Southern
0403709069	unnamed 414-C	Santa Fe Springs	Southern
0403714754	unnamed W-413-E	Santa Fe Springs	Southern
0403714760	Bell W-433-C	Santa Fe Springs	Southern

0403723455	Bell 496-B	Santa Fe Springs	Southern
0403709070	Bell W-431-F	Santa Fe Springs	Southern
0403727224	Bell 400-02	Santa Fe Springs	Southern
0403714762	unnamed 217-B	Santa Fe Springs	Southern
0403727379	Bell 654	Santa Fe Springs	Southern
0403723347	Bell 494-C	Santa Fe Springs	Southern
0403700099	Bell 421-N	Santa Fe Springs	Southern
0403714451	Rosecrans 1	Rosecrans	Southern
0403715012	Rosecrans 32	Rosecrans	Southern
0403714452	Rosecrans 2	Rosecrans	Southern
0403714591	Wolfe 1	Rosecrans, South	Southern
0403714666	Rosecrans 11	Rosecrans	Southern
0403713642	Rosecrans 47	Rosecrans	Southern
0403723668	Trust 19W	Rosecrans	Southern
0403714446	O'Dea 18	Rosecrans	Southern
0403714668	Rosecrans 17	Rosecrans	Southern
0403714667	Rosecrans 16	Rosecrans	Southern
0403723667	O'Dea 26W	Rosecrans	Southern
0403714999	Rosecrans 8	Rosecrans	Southern
0403715014	Rosecrans 35	Rosecrans	Southern

0403714674	Rosecrans 28	Rosecrans	Southern
0403714431	O'Dea 2	Rosecrans	Southern
0403715020	Rosecrans 41	Rosecrans	Southern
0403715015	Rosecrans 36	Rosecrans	Southern
0403714656	Rosecrans A 5-A	Rosecrans	Southern
0403715021	Rosecrans 42	Rosecrans	Southern
0403713643	Trust 1	Rosecrans	Southern

Facility Setting ID	Facility Setting Name	District	Facility (Component) ID	Facility (Component) Name	Facility (Component) Type
90295464	Main Tank Farm	Southern	13440	Divert 2	Tank

Attachment B

Definitions and Authorities

Definitions

PRC section 3008, subdivision (a), defines “well” to mean, among other things, “any oil or gas well or well for the discovery of oil or gas; any well on lands producing or reasonably presumed to contain oil or gas.”

PRC section 3009 defines “operator” to mean “a person who, by virtue of ownership, or under the authority of a lease or any other agreement, has the right to drill, operate, maintain, or control a well or production facility.”

PRC section 3010 defines “production facility” to mean “any equipment attendant to oil and gas production or injection operations including, but not limited to, tanks, flowlines, headers, gathering lines, wellheads, heater treaters, pumps, valves, compressors, injection equipment, and pipelines that are not under the jurisdiction of the State Fire Marshal pursuant to Section 51010 of the Government Code.” (See also Regulations, § 1760, subd. (r).)

Regulations section 1720, subdivision (a), defines critical well to mean a well within: 300 feet of any building intended for human occupancy that is not necessary to the operation of the well or any airport runway; or 100 feet of any dedicated public street, highway, or nearest rail of an operating railway that is in general use, any navigable body of water or watercourse perennially covered by water, any public recreational facility such as a golf course, amusement park, picnic ground, campground, or any other area of periodic high-density population, or any officially recognized wildlife preserve.

Regulations section 1760, subdivision (f), defines environmentally sensitive as any of the following:

(1) A production facility within 300 feet of any public recreational area, or a building intended for human occupancy that is not necessary to the operation of the production operation, such as residences, schools, hospitals, and businesses.

(2) A production facility within 200 feet of any officially recognized wildlife preserve or environmentally sensitive habitat that is designated on a United States Geological Survey

1 topographical map, designated waterways, or other surface waters such as lakes, reservoirs,
2 rivers, canals, creeks, or other water bodies that contain water throughout the year.

3 (3) A production facility within the coastal zone as defined in Section 30103(b) of the
4 Public Resources Code.

5 (4) Any production facility which the Supervisor determines may be a significant
6 potential threat to life, health, property, or natural resources in the event of a leak, or that has
7 a history of chronic leaks.

8 **Regulations section 1760, subdivision (y)**, defines urban area as a cohesive area of at
9 least twenty-five business establishments, residences, or combination thereof, the perimeter of
10 which is 300 feet beyond the outer limits of the outermost structures.

11 **Regulations section 1765.1, subdivision (b)** provides, in relevant part, that a health
12 protection zone means the area within 3,200 feet of a sensitive receptor.

13 **Regulations section 1765.1, subdivision (c)** defines, in relevant part, that a sensitive
14 receptor includes a residence, an educational facility, community center, a health care
15 facility, live-in housing and any business that is open to the public.

16 **State Oil and Gas Supervisor Authority**

17 **PRC section 3013** provides “this division shall be liberally construed to meet its purposes,
18 and the director and the supervisor, acting with the approval of the director, shall have all
19 powers, including the authority to adopt rules and regulations, which may be necessary to
20 carry out the purposes of this division.”

21 **PRC section 3106** authorizes the Supervisor to supervise the drilling, operation,
22 maintenance, and abandonment of oil and gas wells to “prevent, as far as possible, damage
23 to life, health, property, and natural resources; damage to underground oil and gas deposits
24 from infiltrating water and other causes; loss of oil, gas, or reservoir energy, and damage to
25 underground and surface waters suitable for irrigation or domestic purposes by the infiltration
26 of, or the addition of, detrimental substances.”
27
28

1 **PRC section 3224** mandates that the Supervisor “order such tests or remedial work as in
2 his judgment are necessary to prevent damage to life, health, property, and natural resources;
3 to protect oil and gas deposits from damage by underground water; or to prevent the escape
4 of water into underground formations, or to prevent the infiltration of detrimental substances
5 into underground or surface water suitable for irrigation or domestic purposes, to the best
6 interests of the neighboring property owners and the public.”

7 **PRC section 3225**, in relevant part, provides that “an order of the supervisor or a district
8 deputy issued pursuant to this chapter shall provide a clear and concise recitation of the acts
9 or omissions with which the operator is charged. The order shall state all penalties and
10 requirements imposed on the operator in connection with the acts or omissions charged and
11 the order shall provide references to the provisions of this code and the regulations that
12 support the imposition of the penalties and requirements. An order of the supervisor or a district
13 deputy shall be in writing and shall be served on the operator by personal service or by
14 certified mail. When the supervisor or a district deputy issues a written order concerning an
15 operation, an appeal may be made from the order pursuant to the procedures contained in
16 Article 6 (commencing with Section 3350). The order shall inform the operator of its right to
17 appeal the order.”

18 **PRC section 3226, subdivision (a)**, provides that “within 30 days after service of an order
19 pursuant to Sections 3224 and 3225, or Section 3237, or if there has been an appeal from the
20 order to the director, within 30 days after service of the decision of the director, or if a review
21 has been taken of the order of the director, within 10 days after affirmance of the order, the
22 owner or operator shall commence in good faith the work ordered and continue it until
23 completion. If the work has not been commenced and continued to completion, the
24 supervisor may appoint necessary agents to enter the premises and perform the work. An
25 accurate account of the expenditures shall be kept. Any amount so expended shall constitute
26 a lien against real or personal property of the operator pursuant to the provisions of Section
27 3423. Before performing such work, the division may impose a lien against the real or personal
28 property of the operator pursuant to Section 3423 in an amount equal to an estimate of the

1 cost of the work based on a bid from a contractor or previous costs to perform comparable
2 work.”

3 **PRC section 3236.5** authorizes the Supervisor to impose a civil penalty on a person who
4 violates any statutory provision in Chapter 1 of Division 3 of the PRC (PRC sections 3000 through
5 3473), or any regulation that implements those statutory provisions. Subject to the Supervisor’s
6 discretion, the penalty amount may be up to \$25,000 per violation, per day.

7 **PRC section 3270** mandates that CalGEM prescribe by regulation minimum facility
8 maintenance standards for all production facilities in the state.

9 **Regulations section 1722, subdivision (a)** provides all operations shall be conducted in
10 accordance with good oilfield practice.

11 **Regulations section 1777, subdivision (a)** provides that “operators shall maintain
12 production facilities in good condition and in a manner to prevent leakage or corrosion and
13 to safeguard life, health, property, and natural resources.”

14 **Regulations section 1777, subdivision (c)(3)** requires that well cellars are covered and
15 kept drained.

Attachment C

(Inspection Summary ID 12426869)

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspection Summary

Inspection Information					
Inspection ID	Inspection Type	Inspection Date	Inspection Name	Follow-Up Date	
12426869	Environmental Lease Inspection	6/26/2025	Carl Jung		
Compliance Summary					
New Violation(s)		Resolved Violation(s)		Unresolved Violation(s)	
15		0		7	
Operator Information					
Operator Code		Operator Name			
11583		Bridgeland Resources, LLC			
Agent Name		Matt Sanders			
Agent Address		12720 Telegraph Road			
City	Santa Fe Springs	State	CA	Zip Code	90670
Inspected Subject(s)					
See list of Inspected Subjects on subsequent page.					
Inspection Document(s)					
No documents were uploaded during this inspection.					
New Violation(s)					
Notice of Violation According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
Compliance ID:		12426870			
See list of Violations on subsequent page.					
Unresolved Violation(s)					
Notice of Unresolved Violation(s) According to the records maintained by the California Geologic Energy Management Division (CalGEM), Bridgeland Resources, LLC has been found to have not corrected the violation(s) listed below in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
See list of Unresolved Violations on subsequent page.					



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspected Subject(s)					
Field	Lease	Subject ID	Subject Name	Subject Type	Form Name
Santa Fe Springs	unnamed	0403715947	unnamed 051-B	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403715947	unnamed 051-B	Well	Miscellaneous Inspection Form
Santa Fe Springs	unnamed	0403714753	unnamed 415-E	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403714770	unnamed W-200-C	Well	UIC Well Inspection
Santa Fe Springs	unnamed	0403714756	unnamed W-403-C	Well	UIC Well Inspection
Santa Fe Springs	unnamed	0403714778	unnamed 410-C	Well	UIC Well Inspection
Santa Fe Springs	unnamed	0403700094	unnamed W-203-C	Well	UIC Well Inspection
Santa Fe Springs	unnamed	0403709048	unnamed 409-C	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403714761	unnamed W-401-C	Well	UIC Well Inspection
Santa Fe Springs	unnamed	0403714754	unnamed W-413-E	Well	UIC Well Inspection
Santa Fe Springs	unnamed	0403709069	unnamed 414-C	Well	Environmental Well Site Inspection



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

New Violation(s)

Notice Of Violation

According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:

12426870

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12426875	1722(a) - General	California Code of Regulations - Title 14	unnamed W-403-C	0403714756	7/31/2025
Comment		CCR 1722 (a) Weeds are growing close to the well. Reviewed by MM 7/3/2025			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12426876	1722(a) - General	California Code of Regulations - Title 14	unnamed W-200-C	0403714770	7/31/2025
Comment		CCR 1722 (a) Weeds are growing close to the well. Reviewed by MM 7/3/2025			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12426878	1722(a) - General	California Code of Regulations - Title 14	unnamed 415-E	0403714753	7/31/2025
Comment		CCR 1722 (a) Weeds are growing close to the well. Reviewed by MM 7/3/2025			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12426880	1722(a) - General	California Code of Regulations - Title 14	unnamed W-203-C	0403700094	7/31/2025
Comment		CCR 1722 (a) Weeds are growing close to the well. Reviewed by MM 7/3/2025			
Corrective Actions:		Bring into compliance			

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12426885	1722(a) - General	California Code of Regulations - Title 14	unnamed W-413-E	0403714754	7/31/2025
Comment		CCR 1722 (a) Weeds are growing close to the well. Reviewed by MM 7/3/2025			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12426873	1775(c) - Oilfield Wastes and Refuse	California Code of Regulations - Title 14	unnamed 051-B	0403715947	7/31/2025
Comment		CCR 1775 (c) Cellar contained wood planks. Reviewed by MM 7/3/2025			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12426872	1777(a) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	unnamed 051-B	0403715947	7/31/2025
Comment		CCR 1777 (a) Well appeared to be leaking oil at the time of inspection. Reviewed by MM 7/3/2025			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12426871	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	unnamed 051-B	0403715947	7/31/2025
Comment		CCR 1777 (c)(3) Cellar contained significant amounts of what appeared to be crude oil during the time of inspection. Reviewed by MM 7/3/2025			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12426874	1777(c)(3) -	California Code of	unnamed 410-C	0403714778	7/31/2025

	Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	Regulations - Title 14			
Comment		CCR 1777 (c)(3) Cellar contained substantial amounts of water during the time of inspection. Reviewed by MM 7/3/2025			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12426877	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	unnamed W-200-C	0403714770	7/31/2025
Comment		CCR 1777 (c)(3) Cellar contained substantial amounts of water during the time of inspection. Reviewed by MM 7/3/2025			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12426879	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	unnamed 415-E	0403714753	7/31/2025
Comment		CCR 1777 (c)(3) Cellar contained substantial amounts of water during the time of inspection. Reviewed by MM 7/3/2025			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12426881	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	unnamed 409-C	0403709048	7/31/2025
Comment		CCR 1777 (c)(3) Cellar contained substantial amounts of water during the time of inspection.			

		Reviewed by MM 7/3/2025			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12426882	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	unnamed W-401-C	0403714761	7/31/2025
Comment		CCR 1777 (c)(3) Cellar contained substantial amounts of water during the time of inspection. Reviewed by MM 7/3/2025			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12426883	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	unnamed 414-C	0403709069	7/31/2025
Comment		CCR 1777 (c)(3) Cellar contained substantial amounts of water during the time of inspection. Reviewed by MM 7/3/2025			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12426884	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	unnamed W-413-E	0403714754	7/31/2025
Comment		CCR 1777 (c)(3) Cellar contained substantial amounts of water during the time of inspection. Reviewed by MM 7/3/2025			
Corrective Actions:		Bring into compliance			



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Unresolved Violation(s)

Notice of Unresolved Violation(s)

According to the records maintained by the California Geologic Energy Management Division (CalGEM), Bridgeland Resources, LLC has been found to have not corrected the violation(s) listed below in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:	12309222			
Violation ID	Section	Code Type	Subject Name	Subject ID
12309608	1772.1(a)(1) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 414-C	0403709069
Compliance ID:	12365226			
Violation ID	Section	Code Type	Subject Name	Subject ID
12365469	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 415-E	0403714753
12365471	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 409-C	0403709048
Compliance ID:	12320497			
Violation ID	Section	Code Type	Subject Name	Subject ID
12367331	1772.1(a)(2) - Testing of Idle Wells		unnamed 414-C	0403709069
12367346	1772.1(a)(3) - Testing of Idle Wells		unnamed 414-C	0403709069
12369180	1772.1(b) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 414-C	0403709069
Compliance ID:	12422352			
Violation ID	Section	Code Type	Subject Name	Subject ID
12422363	1772.1.2(i) - Idle Well Engineering Analysis for 15-year Idle wells	California Code of Regulations - Title 14	unnamed 414-C	0403709069

Attachment D

(Inspection Summary ID 12421445)

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspection Summary

Inspection Information					
Inspection ID	Inspection Type	Inspection Date	Inspection Name	Follow-Up Date	
12421445	Environmental Lease Inspection	5/15/2025	Jose Trinidad		
Compliance Summary					
New Violation(s)		Resolved Violation(s)		Unresolved Violation(s)	
2		0		0	
Operator Information					
Operator Code		Operator Name			
11583		Bridgeland Resources, LLC			
Agent Name		Matt Sanders			
Agent Address		12720 Telegraph Road			
City	Santa Fe Springs	State	CA	Zip Code	90670
Inspected Subject(s)					
See list of Inspected Subjects on subsequent page.					
Inspection Document(s)					
No documents were uploaded during this inspection.					
New Violation(s)					
Notice of Violation According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
Compliance ID:		12421446			
See list of Violations on subsequent page.					



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspected Subject(s)					
Field	Lease	Subject ID	Subject Name	Subject Type	Form Name
Santa Fe Springs	Santa Fe	90295464	Main Tank Farm	Setting	Environmental Facility Inspection
Santa Fe Springs	Santa Fe	13438	Cone Bottom 4 (solids reject)	Tank	Environmental Facility Inspection
Santa Fe Springs	Santa Fe	17689	WEMCO 1	Vessel	Environmental Facility Inspection
Santa Fe Springs	Santa Fe	13444	Produced Water Tank 2/Surge 6	Tank	Environmental Facility Inspection
Santa Fe Springs	Santa Fe	17676	FWKO #2	Vessel	Environmental Facility Inspection
Santa Fe Springs	Santa Fe	13443	Clarifier 5 T-110	Tank	Environmental Facility Inspection
Santa Fe Springs	Santa Fe	17690	WEMCO 2 (New WEMCO)	Vessel	Environmental Facility Inspection
Santa Fe Springs	Santa Fe	13437	Reject/LACT 3	Tank	Environmental Facility Inspection
Santa Fe Springs	Santa Fe	17675	FWKO #1	Vessel	Environmental Facility Inspection
Santa Fe Springs	Santa Fe	13445	Produced Water Tank 1/Surge 7	Tank	Environmental Facility Inspection
Santa Fe Springs	Santa Fe	13441	Divert 3	Tank	Environmental Facility Inspection
Santa Fe Springs	Santa Fe	13439	Divert 1	Tank	Environmental Facility Inspection
Santa Fe Springs	Santa Fe	19607	Surge 2	Tank	Environmental Facility Inspection
Santa Fe Springs	Santa Fe	19606	Surge 1	Tank	Environmental Facility Inspection
Santa Fe Springs	Santa Fe	13435	LACT 1 Crude Oil	Tank	Environmental Facility Inspection
Santa Fe Springs	Santa Fe	13440	Divert 2	Tank	Environmental Facility Inspection
Santa Fe Springs	Santa Fe	13442	Divert 4	Tank	Environmental Facility Inspection
Santa Fe Springs	Santa Fe	13436	LACT 2 Crude Oil	Tank	Environmental Facility Inspection



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

New Violation(s)

Notice Of Violation

According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:

12421446

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12421448	1777(a) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Divert 2	13440	6/22/2025

Comment

Tank appears to be leaking. CCR 1777(a). Reviewed by MM 2/22/25.

Corrective Actions:

Bring into compliance.

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12421447	1775(a) - Oilfield Wastes and Refuse	California Code of Regulations - Title 14	Main Tank Farm	90295464	6/23/2025

Comment

Oil field refuse. CCR 1775(a). Reviewed by MM 5/22/25.

Corrective Actions:

Bring into compliance.

Attachment E

(Inspection Summary ID 12421269)

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspection Summary

Inspection Information					
Inspection ID	Inspection Type	Inspection Date	Inspection Name	Follow-Up Date	
12421269	Environmental Lease Inspection	5/16/2025	Carl Jung		
Compliance Summary					
New Violation(s)		Resolved Violation(s)		Unresolved Violation(s)	
4		0		2	
Operator Information					
Operator Code		Operator Name			
11583		Bridgeland Resources, LLC			
Agent Name		Matt Sanders			
Agent Address		12720 Telegraph Road			
City	Santa Fe Springs	State	CA	Zip Code	90670
Inspected Subject(s)					
See list of Inspected Subjects on subsequent page.					
Inspection Document(s)					
No documents were uploaded during this inspection.					
New Violation(s)					
Notice of Violation According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
Compliance ID:		12421270			
See list of Violations on subsequent page.					
Unresolved Violation(s)					
Notice of Unresolved Violation(s) According to the records maintained by the California Geologic Energy Management Division (CalGEM), Bridgeland Resources, LLC has been found to have not corrected the violation(s) listed below in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
See list of Unresolved Violations on subsequent page.					



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
Sacramento, CA. 95814
T: (916) 445-5986

Inspected Subject(s)					
Field	Lease	Subject ID	Subject Name	Subject Type	Form Name
Santa Fe Springs	Off	0403716222	Off 773-M	Well	Environmental Well Site Inspection
Santa Fe Springs	Off	0403716222	Off 773-M	Well	Miscellaneous Inspection Form
Santa Fe Springs	Santa Fe	0403716029	Santa Fe 768-B	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe	0403716029	Santa Fe 768-B	Well	Miscellaneous Inspection Form



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

New Violation(s)

Notice Of Violation

According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:

12421270

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12421272	1775(c) - Oilfield Wastes and Refuse	California Code of Regulations - Title 14	Off 773-M	0403716222	6/13/2025
Comment		CCR 1775 (c) There were wooden planks and spare parts in the cellar during the time of inspection. Reviewed by BK			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12421274	1775(c) - Oilfield Wastes and Refuse	California Code of Regulations - Title 14	Santa Fe 768-B	0403716029	6/13/2025
Comment		CCR 1775 (c) There were wooden planks and spare parts in the cellar during the time of inspection. Reviewed by BK			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12421271	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Off 773-M	0403716222	6/13/2025
Comment		CCR 1777 (c)(3) There appeared to be crude oil mixed with sludge in the cellar at the time of inspection. Reviewed by BK			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12421273	1777(c)(3) - Maintenance and	California Code of Regulations - Title	Santa Fe 768-B	0403716029	6/13/2025

	Monitoring of Production Facilities, Safety Systems, and Equipment	14			
Comment		CCR 1777 (c)(3) There appeared to be crude oil mixed with sludge in the cellar at the time of inspection. Reviewed by BK			
Corrective Actions:		Bring into compliance			



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Unresolved Violation(s)

Notice of Unresolved Violation(s)

According to the records maintained by the California Geologic Energy Management Division (CalGEM), Bridgeland Resources, LLC has been found to have not corrected the violation(s) listed below in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:	12298303			
Violation ID	Section	Code Type	Subject Name	Subject ID
12298353	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 768-B	0403716029
Compliance ID:	12354726			
Violation ID	Section	Code Type	Subject Name	Subject ID
12354751	1772.1(b) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 768-B	0403716029

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

Attachment F
(Inspection Summary ID 12424018)



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspection Summary

Inspection Information					
Inspection ID	Inspection Type	Inspection Date	Inspection Name	Follow-Up Date	
12424018	Environmental Lease Inspection	5/19/2025	RJ Mejia		
Compliance Summary					
New Violation(s)		Resolved Violation(s)		Unresolved Violation(s)	
7		0		19	
Operator Information					
Operator Code		Operator Name			
11583		Bridgeland Resources, LLC			
Agent Name		Matt Sanders			
Agent Address		12720 Telegraph Road			
City	Santa Fe Springs	State	CA	Zip Code	90670
Inspected Subject(s)					
See list of Inspected Subjects on subsequent page.					
Inspection Document(s)					
No documents were uploaded during this inspection.					
New Violation(s)					
Notice of Violation According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
Compliance ID:		12424019			
See list of Violations on subsequent page.					
Unresolved Violation(s)					
Notice of Unresolved Violation(s) According to the records maintained by the California Geologic Energy Management Division (CalGEM), Bridgeland Resources, LLC has been found to have not corrected the violation(s) listed below in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
See list of Unresolved Violations on subsequent page.					



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspected Subject(s)					
Field	Lease	Subject ID	Subject Name	Subject Type	Form Name
Santa Fe Springs	Santa Fe	0403716728	Santa Fe 812-C	Well	UIC Well Inspection
Santa Fe Springs	unnamed	0403715634	unnamed 826-C	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403715640	unnamed 821-M	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403716724	unnamed 820-C	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403729991	unnamed 857	Well	UIC Well Inspection
Santa Fe Springs	unnamed	0403715700	unnamed 834-N	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403716727	unnamed W-823-C	Well	UIC Well Inspection
Santa Fe Springs	unnamed	0403726691	unnamed 854-C	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403716722	unnamed 819-C	Well	Environmental Well Site Inspection
Santa Fe Springs	Off	0403716009	Off W-761-F	Well	UIC Well Inspection
Santa Fe Springs	unnamed	0403729994	unnamed 860	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403726997	unnamed 647	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403729987	unnamed 656	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403715688	unnamed 831-E	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403729990	unnamed 856	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403715653	unnamed 829-C	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403729992	unnamed 858	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403715646	unnamed W839-C	Well	UIC Well Inspection
Santa Fe Springs	unnamed	0403715698	unnamed 841-E	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403715647	unnamed W-846-B	Well	UIC Well

					Inspection
Santa Fe Springs	unnamed	0403715659	unnamed 843-E	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403726486	unnamed 852-F	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe	0403716710	Santa Fe 811-B	Well	UIC Well Inspection
Santa Fe Springs	unnamed	0403715661	unnamed 835-C	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe	0403716723	Santa Fe W-814-C	Well	UIC Well Inspection
Santa Fe Springs	unnamed	0403715648	unnamed 848-N	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403715638	unnamed 849-E	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403729993	unnamed 859	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403715687	unnamed 830-B	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403715701	unnamed 838-N	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403716712	unnamed 815-C	Well	Environmental Well Site Inspection
Santa Fe Springs	Off	0403715991	Off 760-B	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403715658	unnamed 837-B	Well	Environmental Well Site Inspection
Santa Fe Springs	Off	0403716007	Off W-748-G	Well	UIC Well Inspection
Santa Fe Springs	unnamed	0403715689	unnamed W-828-J	Well	UIC Well Inspection
Santa Fe Springs	Santa Fe	0403716713	Santa Fe W-806-C	Well	UIC Well Inspection
Santa Fe Springs	Off	0403715995	Off W-741-P	Well	UIC Well Inspection
Santa Fe Springs	unnamed	0403727146	unnamed 648	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403715639	unnamed W-827-E	Well	UIC Well Inspection



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

New Violation(s)

Notice Of Violation

According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:

12424019

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12424020	1722(a) - General	California Code of Regulations - Title 14	unnamed 820-C	0403716724	6/19/2025
Comment		Weeds observed near the well, during the time of inspection			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12424022	1722(a) - General	California Code of Regulations - Title 14	unnamed 854-C	0403726691	6/19/2025
Comment		Weeds observed near the well, during the time of inspection			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12424023	1722(a) - General	California Code of Regulations - Title 14	unnamed W-823-C	0403716727	6/19/2025
Comment		Weeds observed near the well, during the time of inspection			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12424025	1722(a) - General	California Code of Regulations - Title 14	unnamed 819-C	0403716722	6/19/2025
Comment		Weeds observed near the well, during the time of inspection			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date

12424026	1722(a) - General	California Code of Regulations - Title 14	Santa Fe W-814-C	0403716723	6/19/2025
Comment		Weeds observed near the well, during the time of inspection			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12424021	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	unnamed 831-E	0403715688	6/19/2025
Comment		Well appeared to have Fluid in the Cellar, during the time of inspection.			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12424024	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	unnamed 819-C	0403716722	6/19/2025
Comment		Well appeared to have Fluid in the Cellar, during the time of inspection.			
Corrective Actions:		Bring into compliance			



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Unresolved Violation(s)

Notice of Unresolved Violation(s)

According to the records maintained by the California Geologic Energy Management Division (CalGEM), Bridgeland Resources, LLC has been found to have not corrected the violation(s) listed below in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:	12280929			
Violation ID	Section	Code Type	Subject Name	Subject ID
12282463	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Off W-761-F	0403716009
Compliance ID:	12309222			
Violation ID	Section	Code Type	Subject Name	Subject ID
12309562	1772.1(a)(1) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 848-N	0403715648
Compliance ID:	12313709			
Violation ID	Section	Code Type	Subject Name	Subject ID
12314471	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 648	0403727146
12314478	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 849-E	0403715638
Compliance ID:	12332105			
Violation ID	Section	Code Type	Subject Name	Subject ID
12332535	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 815-C	0403716712
Compliance ID:	12350772			
Violation ID	Section	Code Type	Subject Name	Subject ID
12350968	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Off 760-B	0403715991
Compliance ID:	12354726			
Violation ID	Section	Code Type	Subject Name	Subject ID
12354731	1772.1(b) - Testing of Idle Wells	California Code of Regulations - Title 14	Off W-761-F	0403716009
12354736	1772.1(b) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 648	0403727146
Compliance ID:	12357161			
Violation ID	Section	Code Type	Subject Name	Subject ID
12357201	1772.1(a)(1) - Testing of Idle Wells	California Code of Regulations - Title 14	Off 760-B	0403715991

Compliance ID:	12372187			
Violation ID	Section	Code Type	Subject Name	Subject ID
12372265	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 819-C	0403716722
12372266	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 820-C	0403716724
12372267	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 820-C	0403716724
Compliance ID:	12372186			
Violation ID	Section	Code Type	Subject Name	Subject ID
12372963	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 819-C	0403716722
12372964	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 820-C	0403716724
12372965	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 820-C	0403716724
Compliance ID:	12384316			
Violation ID	Section	Code Type	Subject Name	Subject ID
12384438	1772.1(b) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 849-E	0403715638
Compliance ID:	12392035			
Violation ID	Section	Code Type	Subject Name	Subject ID
12392069	1772.1(b) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 815-C	0403716712
Compliance ID:	12397957			
Violation ID	Section	Code Type	Subject Name	Subject ID
12398170	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe W-814-C	0403716723
Compliance ID:	12411531			
Violation ID	Section	Code Type	Subject Name	Subject ID
12411579	1772.1(b) - Testing of Idle Wells	California Code of Regulations - Title 14	Off 760-B	0403715991

Attachment G

(Inspection Summary ID 12424121)

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspection Summary

Inspection Information					
Inspection ID	Inspection Type	Inspection Date	Inspection Name	Follow-Up Date	
12424121	Environmental Lease Inspection	6/11/2025	Javier Vasquez		
Compliance Summary					
New Violation(s)		Resolved Violation(s)		Unresolved Violation(s)	
3		0		34	
Operator Information					
Operator Code		Operator Name			
11583		Bridgeland Resources, LLC			
Agent Name		Matt Sanders			
Agent Address		12720 Telegraph Road			
City	Santa Fe Springs	State	CA	Zip Code	90670
Inspected Subject(s)					
See list of Inspected Subjects on subsequent page.					
Inspection Document(s)					
No documents were uploaded during this inspection.					
New Violation(s)					
Notice of Violation According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
Compliance ID:		12424122			
See list of Violations on subsequent page.					
Unresolved Violation(s)					
Notice of Unresolved Violation(s) According to the records maintained by the California Geologic Energy Management Division (CalGEM), Bridgeland Resources, LLC has been found to have not corrected the violation(s) listed below in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
See list of Unresolved Violations on subsequent page.					



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspected Subject(s)					
Field	Lease	Subject ID	Subject Name	Subject Type	Form Name
Santa Fe Springs	Santa Fe	0403715723	Santa Fe 519-E	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe	0403715746	Santa Fe 736-F	Well	Environmental Well Site Inspection
Santa Fe Springs	Anderson	0403715715	Anderson 533-N	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe	0403723590	Santa Fe W-786-L	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe	0403715745	Santa Fe W-737-F	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe	0403715726	Santa Fe W-517-P	Well	Environmental Well Site Inspection
Santa Fe Springs		0403723163	714B	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe	0403723164	Santa Fe 783-B	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403715513	Bell W-511-P	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe	0403716258	Santa Fe W-712-C	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe	0403715725	Santa Fe 513-C	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe	0403723588	Santa Fe W-784-T	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe	0403715739	Santa Fe 710-C	Well	Environmental Well Site Inspection
Santa Fe Springs	Baker-Humble 2	0403723111	Baker-Humble 2 10	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe	0403716269	Santa Fe W-728-G	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe	0403716020	Santa Fe W-707-C	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe	0403716267	Santa Fe 717-P	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe	0403723589	Santa Fe W-785-T	Well	Environmental Well Site Inspection
Santa Fe Springs	Baker-Humble 2	0403722913	Baker-Humble 2 8R	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe	0403716034	Santa Fe 729-B	Well	Environmental Well

					Site Inspection
Santa Fe Springs	Bell	0403715467	Bell W-510-C	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe	0403715720	Santa Fe 518G	Well	Environmental Well Site Inspection
Santa Fe Springs	Babonet	0403723351	Babonet W-935-C	Well	Environmental Well Site Inspection



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

New Violation(s)

Notice Of Violation

According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:

12424122

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12424123	1775(c) - Oilfield Wastes and Refuse	California Code of Regulations - Title 14	Santa Fe 519-E	0403715723	7/11/2025
Comment		Debris/oily wooden planks inside cellar. Reviewed by BK on 6/11/2025.			
Corrective Actions:		Bring into Compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12424124	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Santa Fe 519-E	0403715723	7/11/2025
Comment		Fluid observed in cellar. No immediate source identified for the fluid. Reviewed by BK on 6/11/2025			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12424125	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Santa Fe 717-P	0403716267	7/11/2025
Comment		Fluid observed in cellar and no immediate source identified. Reviewed by BK on 6/11/2025.			
Corrective Actions:		Bring into compliance			



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
Sacramento, CA. 95814
T: (916) 445-5986

Unresolved Violation(s)

Notice of Unresolved Violation(s)

According to the records maintained by the California Geologic Energy Management Division (CalGEM), Bridgeland Resources, LLC has been found to have not corrected the violation(s) listed below in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:	12309240			
Violation ID	Section	Code Type	Subject Name	Subject ID
12309618	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 717-P	0403716267
Compliance ID:	12313691			
Violation ID	Section	Code Type	Subject Name	Subject ID
12314453	1772.1(a)(1) - Testing of Idle Wells	California Code of Regulations - Title 14	Baker-Humble 2 10	0403723111
Compliance ID:	12313709			
Violation ID	Section	Code Type	Subject Name	Subject ID
12314475	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Baker-Humble 2 10	0403723111
12314486	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Anderson 533-N	0403715715
Compliance ID:	12321914			
Violation ID	Section	Code Type	Subject Name	Subject ID
12322150	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe W-737-F	0403715745
Compliance ID:	12357161			
Violation ID	Section	Code Type	Subject Name	Subject ID
12357179	1772.1(a)(1) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 783-B	0403723164
12357180	1772.1(a)(1) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 518G	0403715720
12357181	1772.1(a)(1) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 513-C	0403715725
12357183	1772.1(a)(1) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 729-B	0403716034
Compliance ID:	12365226			
Violation ID	Section	Code Type	Subject Name	Subject ID
12365470	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 736-F	0403715746

Compliance ID:	12320497			
Violation ID	Section	Code Type	Subject Name	Subject ID
12367337	1772.1(a)(2) - Testing of Idle Wells		Santa Fe 710-C	0403715739
12367352	1772.1(a)(3) - Testing of Idle Wells		Santa Fe 710-C	0403715739
12369186	1772.1(b) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 710-C	0403715739
Compliance ID:	12372187			
Violation ID	Section	Code Type	Subject Name	Subject ID
12372257	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 518G	0403715720
12372258	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 518G	0403715720
12372263	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 729-B	0403716034
12372264	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 729-B	0403716034
12372268	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Baker-Humble 2 8R	0403722913
12372269	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	Baker-Humble 2 8R	0403722913
12372270	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 783-B	0403723164
12372271	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 783-B	0403723164
Compliance ID:	12372186			
Violation ID	Section	Code Type	Subject Name	Subject ID
12372955	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 518G	0403715720
12372956	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 518G	0403715720
12372961	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 729-B	0403716034
12372962	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 729-B	0403716034
12372966	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Baker-Humble 2 8R	0403722913
12372967	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	Baker-Humble 2 8R	0403722913
12372968	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 783-B	0403723164
12372969	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 783-B	0403723164
Compliance ID:	12384316			

Violation ID	Section	Code Type	Subject Name	Subject ID
12384426	1772.1(b) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe 717-P	0403716267
12384432	1772.1(b) - Testing of Idle Wells	California Code of Regulations - Title 14	Anderson 533-N	0403715715
12384439	1772.1(b) - Testing of Idle Wells	California Code of Regulations - Title 14	Baker-Humble 2 10	0403723111
12384445	1772.1(b) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe W-737-F	0403715745
Compliance ID:	12388643			
Violation ID	Section	Code Type	Subject Name	Subject ID
12388837	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Santa Fe W-786-L	0403723590

Attachment H

(Inspection Summary ID 12424593)

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspection Summary

Inspection Information					
Inspection ID	Inspection Type	Inspection Date	Inspection Name	Follow-Up Date	
12424593	Environmental Lease Inspection	6/11/2025	Carl Jung		
Compliance Summary					
New Violation(s)		Resolved Violation(s)		Unresolved Violation(s)	
5		0		5	
Operator Information					
Operator Code		Operator Name			
11583		Bridgeland Resources, LLC			
Agent Name		Matt Sanders			
Agent Address		12720 Telegraph Road			
City	Santa Fe Springs	State	CA	Zip Code	90670
Inspected Subject(s)					
See list of Inspected Subjects on subsequent page.					
Inspection Document(s)					
No documents were uploaded during this inspection.					
New Violation(s)					
Notice of Violation According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
Compliance ID:		12424594			
See list of Violations on subsequent page.					
Unresolved Violation(s)					
Notice of Unresolved Violation(s) According to the records maintained by the California Geologic Energy Management Division (CalGEM), Bridgeland Resources, LLC has been found to have not corrected the violation(s) listed below in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
See list of Unresolved Violations on subsequent page.					



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
Sacramento, CA. 95814
T: (916) 445-5986

Inspected Subject(s)					
Field	Lease	Subject ID	Subject Name	Subject Type	Form Name
Santa Fe Springs	unnamed	0403715968	unnamed 637-E	Well	Environmental Well Site Inspection
Santa Fe Springs	Anderson	0403715983	Anderson 557-C	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403715696	unnamed W-638-N	Well	UIC Well Inspection
Santa Fe Springs	Anderson	0403715797	Anderson 538-P	Well	Environmental Well Site Inspection
Santa Fe Springs	Anderson	0403715712	Anderson W-530-G	Well	UIC Well Inspection



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

New Violation(s)

Notice Of Violation

According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:

12424594

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12424596	1777(b)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Anderson 557-C	0403715983	7/11/2025

Comment

CCR 1777 (c)(3) The cellar was filled with a substantial amount of water during the time of inspection.

Reviewed by BK 6/13/2025.

Corrective Actions:

Bring into compliance

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12424595	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	unnamed 637-E	0403715968	7/11/2025

Comment

CCR 1777 (c)(3) The cellar was filled with a substantial amount of water during the time of inspection.

Reviewed by BK 6/13/2025.

Corrective Actions:

Bring into compliance

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12424597	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety	California Code of Regulations - Title 14	Anderson 538-P	0403715797	7/11/2025

	Systems, and Equipment				
Comment		CCR 1777 (c)(3) The cellar was filled with a substantial amount of water during the time of inspection. Reviewed by BK 6/13/2025.			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12424598	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	unnamed W-638-N	0403715696	7/11/2025
Comment		CCR 1777 (c)(3) The cellar was filled with a substantial amount of water during the time of inspection. Reviewed by BK 6/13/2025.			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12424599	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Anderson W-530-G	0403715712	7/11/2025
Comment		CCR 1777 (c)(3) The cellar was filled with a substantial amount of water during the time of inspection. Reviewed by BK 6/13/2025.			
Corrective Actions:		Bring into compliance			



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Unresolved Violation(s)

Notice of Unresolved Violation(s)

According to the records maintained by the California Geologic Energy Management Division (CalGEM), Bridgeland Resources, LLC has been found to have not corrected the violation(s) listed below in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:	12309222			
Violation ID	Section	Code Type	Subject Name	Subject ID
12309574	1772.1(a)(1) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 637-E	0403715968
Compliance ID:	12313709			
Violation ID	Section	Code Type	Subject Name	Subject ID
12314489	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 637-E	0403715968
Compliance ID:	12320497			
Violation ID	Section	Code Type	Subject Name	Subject ID
12367341	1772.1(a)(2) - Testing of Idle Wells		Anderson W-530-G	0403715712
12369185	1772.1(b) - Testing of Idle Wells	California Code of Regulations - Title 14	Anderson W-530-G	0403715712
Compliance ID:	12384316			
Violation ID	Section	Code Type	Subject Name	Subject ID
12384431	1772.1(b) - Testing of Idle Wells	California Code of Regulations - Title 14	unnamed 637-E	0403715968

Attachment I

(Inspection Summary ID 12424607)

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspection Summary

Inspection Information					
Inspection ID	Inspection Type	Inspection Date	Inspection Name	Follow-Up Date	
12424607	Environmental Lease Inspection	6/16/2025	Carl Jung		
Compliance Summary					
New Violation(s)		Resolved Violation(s)		Unresolved Violation(s)	
3		0		0	
Operator Information					
Operator Code		Operator Name			
11583		Bridgeland Resources, LLC			
Agent Name		Matt Sanders			
Agent Address		12720 Telegraph Road			
City	Santa Fe Springs	State	CA	Zip Code	90670
Inspected Subject(s)					
See list of Inspected Subjects on subsequent page.					
Inspection Document(s)					
No documents were uploaded during this inspection.					
New Violation(s)					
Notice of Violation According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
Compliance ID:		12424608			
See list of Violations on subsequent page.					



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
Sacramento, CA. 95814
T: (916) 445-5986

Inspected Subject(s)					
Field	Lease	Subject ID	Subject Name	Subject Type	Form Name
Santa Fe Springs	Bell	0403709042	Bell 446-B	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403709063	Bell 439-F	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403709063	Bell 439-F	Well	Miscellaneous Inspection Form



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

New Violation(s)

Notice Of Violation

According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:

12424608

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12424611	1775(c) - Oilfield Wastes and Refuse	California Code of Regulations - Title 14	Bell 439-F	0403709063	7/14/2025

Comment

CCR 1775 (c) There were wooden planks in the cellar during the time of inspection.
 Reviewed by BK 6/16/2025

Corrective Actions:

Bring into compliance

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12424609	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 446-B	0403709042	7/14/2025

Comment

CCR 1777 (c)(3) There was a substantial amount of water in the cellar during the time of inspection. Reviewed by BK 6/16/2025

Corrective Actions:

Bring into compliance

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12424610	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 439-F	0403709063	7/15/2025

Comment

CCR 1777 (c)(3) There was a substantial amount of water in the cellar during the time of inspection. Reviewed by BK 6/16/2025

Corrective Actions:

Bring into compliance

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

Attachment J
(Inspection Summary ID 12425447)



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspection Summary

Inspection Information					
Inspection ID	Inspection Type	Inspection Date	Inspection Name	Follow-Up Date	
12425447	Environmental Lease Inspection	6/18/2025	Jose Trinidad		
Compliance Summary					
New Violation(s)		Resolved Violation(s)		Unresolved Violation(s)	
14		0		1	
Operator Information					
Operator Code		Operator Name			
11583		Bridgeland Resources, LLC			
Agent Name		Matt Sanders			
Agent Address		12720 Telegraph Road			
City	Santa Fe Springs	State	CA	Zip Code	90670
Inspected Subject(s)					
See list of Inspected Subjects on subsequent page.					
Inspection Document(s)					
No documents were uploaded during this inspection.					
New Violation(s)					
Notice of Violation According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
Compliance ID:		12425448			
See list of Violations on subsequent page.					
Unresolved Violation(s)					
Notice of Unresolved Violation(s) According to the records maintained by the California Geologic Energy Management Division (CalGEM), Bridgeland Resources, LLC has been found to have not corrected the violation(s) listed below in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
Compliance ID:		12417880			

Violation ID	Section	Code Type	Subject Name	Subject ID
12417909	1724.10(i)(4) - Underground Injection Control	California Code of Regulations - Title 14	Bell W445F	0403709068



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspected Subject(s)					
Field	Lease	Subject ID	Subject Name	Subject Type	Form Name
Santa Fe Springs	Bell	0403700103	Bell 428-F	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403723601	Bell 498-C	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403727440	Bell 584	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403709036	Bell 434-F	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403714759	Bell 444-B	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403730067	Bell 200-02	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403700102	Bell 429-E	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403709071	Bell 440-L	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403709068	Bell W445F	Well	UIC Well Inspection
Santa Fe Springs	Bell	0403714772	Bell 466-C	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403727214	Bell 583	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403709066	Bell 427-C	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403727368	Bell 650	Well	Environmental Well Site Inspection
Santa Fe Springs	Santa Fe Comm.	0403709040	Santa Fe Comm. 488-E	Well	Environmental Well Site Inspection



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

New Violation(s)

Notice Of Violation

According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:

12425448

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12425450	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 498-C	0403723601	7/18/2025

Comment

Significant amount of fluid in the cellar. CCR 1777(c)(3). Reviewed by BK 06/23/2025.

Corrective Actions:

Bring into compliance.

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12425451	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 444-B	0403714759	7/18/2025

Comment

Significant amount of fluid in the cellar. CCR 1777(c)(3). Reviewed by BK 06/23/2025.

Corrective Actions:

Bring into compliance.

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12425452	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 200-02	0403730067	7/18/2025

Comment

Significant amount of fluid in the cellar. CCR 1777(c)(3). Reviewed by BK 06/23/2025.

Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12425453	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 434-F	0403709036	7/18/2025
Comment		Significant amount of fluid in the cellar. CCR 1777(c)(3). Reviewed by BK 6/23/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12425454	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 584	0403727440	7/18/2025
Comment		Significant amount of fluid in the cellar. CCR 1777(c)(3). Reviewed by BK 06/23/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12425455	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 440-L	0403709071	7/18/2025
Comment		Significant amount of fluid in the cellar with a slight oily film. CCR 1777(c)(3). Reviewed by BK 06/23/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12425456	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 466-C	0403714772	7/18/2025

Comment		Significant amount of fluid in the cellar. CCR 1777(c)(3). Reviewed by BK 06/23/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12425457	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell W445F	0403709068	7/18/2025
Comment		Significant amount of oily fluid in the cellar. CCR 1777(c)(3). Reviewed by BK 06/23/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12425458	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 427-C	0403709066	7/18/2025
Comment		Significant amount of fluid in the cellar. CCR 1777(c)(3). Reviewed by BK 06/23/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12425459	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 429-E	0403700102	7/18/2025
Comment		Significant amount of fluid in the cellar. CCR 1777(c)(3). Reviewed by BK 06/23/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12425460	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 650	0403727368	7/18/2025

Comment		Significant amount of oily fluid in the cellar. CCR 1777(c)(3). Reviewed by BK 06/23/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12425461	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 583	0403727214	7/18/2025
Comment		Significant amount of what appears to be crude oil in the cellar. CCR 1777(c)(3). Reviewed by BK 06/23/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12425462	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Santa Fe Comm. 488-E	0403709040	7/18/2025
Comment		Significant amount of fluid in the cellar. CCR 1777(c)(3). Reviewed by BL 06/23/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12425449	1777(d) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 428-F	0403700103	7/18/2025
Comment		There is a significant opening in the chain-link fence enclosing the urban well. CCR 1777(d). Reviewed by BK 06/23/2025.			
Corrective Actions:		Bring into compliance.			

Attachment K

(Inspection Summary ID 12427988)

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspection Summary

Inspection Information					
Inspection ID	Inspection Type	Inspection Date	Inspection Name	Follow-Up Date	
12427988	Environmental Lease Inspection	6/25/2025	Javier Vasquez		
Compliance Summary					
New Violation(s)		Resolved Violation(s)		Unresolved Violation(s)	
15		0		0	
Operator Information					
Operator Code		Operator Name			
11583		Bridgeland Resources, LLC			
Agent Name		Matt Sanders			
Agent Address		12720 Telegraph Road			
City	Santa Fe Springs	State	CA	Zip Code	90670
Inspected Subject(s)					
See list of Inspected Subjects on subsequent page.					
Inspection Document(s)					
No documents were uploaded during this inspection.					
New Violation(s)					
Notice of Violation According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
Compliance ID:		12427989			
See list of Violations on subsequent page.					



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspected Subject(s)					
Field	Lease	Subject ID	Subject Name	Subject Type	Form Name
Santa Fe Springs	Bell	0403723455	Bell 496-B	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403714760	Bell W-433-C	Well	UIC Well Inspection
Santa Fe Springs	Santa Fe Comm.	0403714769	Santa Fe Comm. 482-D	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403709070	Bell W-431-F	Well	UIC Well Inspection
Santa Fe Springs	Bell	0403727224	Bell 400-02	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403727377	Bell 655	Well	Environmental Well Site Inspection
Santa Fe Springs	unnamed	0403714762	unnamed 217-B	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403727379	Bell 654	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403714779	Bell 452-C	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403723347	Bell 494-C	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403727376	Bell 653	Well	Environmental Well Site Inspection
Santa Fe Springs	Bell	0403700099	Bell 421-N	Well	Environmental Well Site Inspection



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

New Violation(s)

Notice Of Violation

According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:

12427989

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12427992	1722(a) - General	California Code of Regulations - Title 14	Bell 655	0403727377	8/16/2025
Comment		Excessive weed growth and the presence of oily fluids around the well and cellar present a fire hazard and impede access. CCR 1722(a). Reviewed by BK on 7/14/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12427996	1722(a) - General	California Code of Regulations - Title 14	Bell 400-02	0403727224	8/16/2025
Comment		Excessive weed growth and the presence of oily fluids around the well and cellar present a fire hazard and impede access. CCR 1722(a). Reviewed by BK on 7/14/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12427998	1722(a) - General	California Code of Regulations - Title 14	Bell 654	0403727379	8/16/2025
Comment		Weeds growing around and near the cellar creating a potential fire hazard and obstruct access. CCR 1722(a). Reviewed by BK on 7/15/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12428001	1722(a) - General	California Code of Regulations - Title 14	Bell 653	0403727376	8/16/2025
Comment		Excessive weed growth and the presence of oily fluids around the well and cellar present a fire hazard and impede access. CCR 1722(a). Reviewed by BK on 7/14/2025.			

Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12428004	1722(a) - General	California Code of Regulations - Title 14	Bell 452-C	0403714779	8/16/2025
Comment		Excessive weed growth around the well and near the cellar, which obstructs access and can pose a fire hazard. CCR 1722(a). Reviewed by BK on 7/15/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12427993	1775(a) - Oilfield Wastes and Refuse	California Code of Regulations - Title 14	Santa Fe Comm. 482-D	0403714769	8/16/2025
Comment		Oil field refuse, pipes, wooden planks, cables, spare parts etc., left on site, not properly contained or removed. CCR 1775(a). Reviewed by BK on 7/15/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12427990	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 496-B	0403723455	8/16/2025
Comment		Standing water in cellar. CCR 1777(c)(3). Reviewed by BK on 7/15/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12427991	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell W-433-C	0403714760	8/16/2025
Comment		Significant amount of standing water inside cellar, creating a potential risk. CCR 1777(c)(3). Reviewed by BK on 7/15/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12427995	1777(c)(3) - Maintenance and	California Code of Regulations - Title	Bell W-431-F	0403709070	8/16/2025

	Monitoring of Production Facilities, Safety Systems, and Equipment	14			
Comment		Standing water in cellar, creating a potential risk. CCR 1777(c)(3). Reviewed by BK on 7/15/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12427997	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 400-02	0403727224	8/16/2025
Comment		Standing oily water inside cellar, creating a potential risk. CCR 1777(c)(3). Reviewed by BK on 7/15/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12427999	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 654	0403727379	8/16/2025
Comment		Standing water with oily sheen in cellar, creating a potential risk. CCR 1777(c)(3). Reviewed by BK on 7/15/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12428000	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	unnamed 217-B	0403714762	8/16/2025
Comment		Substantial amount of standing fluid in cellar. CCR 1777(c)(3). Reviewed by BK on 7/15/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due

					Date
12428002	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 421-N	0403700099	8/16/2025
Comment		There is a significant amount of what appears to be oily standing water inside the cellar, creating a potential risk. CCR 1777(c)(3). Reviewed by BK on 7/15/2025			
Corrective Actions:		Bring into compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12428003	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Bell 494-C	0403723347	8/16/2025
Comment		Standing water with what appears to be an oily sheen inside cellar, creating a potential risk. CCR 1777(c)(3). Reviewed by BK on 7/15/2025.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12427994	1778(a)(3) - Enclosure Specifications	California Code of Regulations - Title 14	Santa Fe Comm. 482-D	0403714769	8/16/2025
Comment		Inadequate enclosure- has no entrance or access to the well. CCR 1778(a). Reviewed by BK on 7/15/2025.			
Corrective Actions:		Bring into compliance.			

Attachment L
(Inspection Summary ID 124235264)

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspection Summary

Inspection Information					
Inspection ID	Inspection Type	Inspection Date	Inspection Name	Follow-Up Date	
12435264	Environmental Lease Inspection	9/12/2025	Jose Trinidad		
Compliance Summary					
New Violation(s)		Resolved Violation(s)		Unresolved Violation(s)	
4		0		2	
Operator Information					
Operator Code		Operator Name			
11583		Bridgeland Resources, LLC			
Agent Name		Matt Sanders			
Agent Address		12720 Telegraph Road			
City	Santa Fe Springs	State	CA	Zip Code	90670
Inspected Subject(s)					
See list of Inspected Subjects on subsequent page.					
Inspection Document(s)					
No documents were uploaded during this inspection.					
New Violation(s)					
Notice of Violation According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
Compliance ID:		12435265			
See list of Violations on subsequent page.					
Unresolved Violation(s)					
Notice of Unresolved Violation(s) According to the records maintained by the California Geologic Energy Management Division (CalGEM), Bridgeland Resources, LLC has been found to have not corrected the violation(s) listed below in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
See list of Unresolved Violations on subsequent page.					



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
Sacramento, CA. 95814
T: (916) 445-5986

Inspected Subject(s)					
Field	Lease	Subject ID	Subject Name	Subject Type	Form Name
Rosecrans, South	Riverside	0403714568	Riverside 1	Well	Environmental Well Site Inspection
Rosecrans	Rosecrans	0403714452	Rosecrans 2	Well	Environmental Well Site Inspection
Rosecrans	Rosecrans	0403714451	Rosecrans 1	Well	Environmental Well Site Inspection
Rosecrans	Callender	0403714474	Callender 1	Well	Environmental Well Site Inspection



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

New Violation(s)

Notice Of Violation

According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:

12435265

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12435266	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Riverside 1	0403714568	10/13/2025

Comment

Cellar contained significant amount of oil. CCR 1777(c)(3). Reviewed by BK 9/19/25.

Corrective Actions:

Bring into compliance.

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12435267	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Rosecrans 2	0403714452	10/13/2025

Comment

Cellar contained significant amount of fluid. CCR 1777(c)(3). Reviewed by BK 9/19/25.

Corrective Actions:

Bring into compliance.

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12435268	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Callender 1	0403714474	10/13/2025

Comment

Significant amount of oil in the cellar. CCR 1777(c)(3). Reviewed by BK 9/19/25.

Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12435269	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Rosecrans 1	0403714451	10/13/2025
Comment		Cellar contained significant amount of oil. CCR 1777(c)(3). Reviewed by BK 9/19/25.			
Corrective Actions:		Bring into compliance.			



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Unresolved Violation(s)

Notice of Unresolved Violation(s)

According to the records maintained by the California Geologic Energy Management Division (CalGEM), Bridgeland Resources, LLC has been found to have not corrected the violation(s) listed below in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:	12357161			
Violation ID	Section	Code Type	Subject Name	Subject ID
12357186	1772.1(a)(1) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 2	0403714452
Compliance ID:	12422352			
Violation ID	Section	Code Type	Subject Name	Subject ID
12422379	1772.1.2(i) - Idle Well Engineering Analysis for 15-year Idle wells	California Code of Regulations - Title 14	Rosecrans 2	0403714452

Attachment M

(Inspection Summary ID 12425777)

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspection Summary

Inspection Information					
Inspection ID	Inspection Type	Inspection Date	Inspection Name	Follow-Up Date	
12435777	Environmental Lease Inspection	9/18/2025	Melissa Emuh		
Compliance Summary					
New Violation(s)		Resolved Violation(s)		Unresolved Violation(s)	
12		0		6	
Operator Information					
Operator Code		Operator Name			
11583		Bridgeland Resources, LLC			
Agent Name		Matt Sanders			
Agent Address		12720 Telegraph Road			
City	Santa Fe Springs	State	CA	Zip Code	90670
Inspected Subject(s)					
See list of Inspected Subjects on subsequent page.					
Inspection Document(s)					
No documents were uploaded during this inspection.					
New Violation(s)					
Notice of Violation According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
Compliance ID:		12435778			
See list of Violations on subsequent page.					
Unresolved Violation(s)					
Notice of Unresolved Violation(s) According to the records maintained by the California Geologic Energy Management Division (CalGEM), Bridgeland Resources, LLC has been found to have not corrected the violation(s) listed below in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
See list of Unresolved Violations on subsequent page.					



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspected Subject(s)					
Field	Lease	Subject ID	Subject Name	Subject Type	Form Name
Rosecrans	Rosecrans	0403714999	Rosecrans 8	Well	Environmental Well Site Inspection
Rosecrans	Rosecrans	0403714667	Rosecrans 16	Well	Environmental Well Site Inspection
Rosecrans	Rosecrans	0403715004	Rosecrans 14	Well	Environmental Well Site Inspection
Rosecrans	O'Dea	0403723667	O'Dea 26W	Well	UIC Well Inspection
Rosecrans	Rosecrans	0403715025	Rosecrans 50	Well	Environmental Well Site Inspection
Rosecrans	O'Dea	0403714438	O'Dea 8	Well	Environmental Well Site Inspection
Rosecrans	Rosecrans	0403714668	Rosecrans 17	Well	Environmental Well Site Inspection
Rosecrans	O'Dea	0403714446	O'Dea 18	Well	UIC Well Inspection
Rosecrans	Trust	0403723668	Trust 19W	Well	UIC Well Inspection
Rosecrans	Rosecrans	0403714666	Rosecrans 11	Well	Environmental Well Site Inspection
Rosecrans	O'Dea	0403714440	O'Dea 11	Well	Environmental Well Site Inspection
Rosecrans	Rosecrans	0403713642	Rosecrans 47	Well	Environmental Well Site Inspection



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

New Violation(s)

Notice Of Violation

According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:

12435778

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12435781	1722(a) - General	California Code of Regulations - Title 14	Rosecrans 14	0403715004	10/20/2025
Comment		Weeds in cellar. Reviewed by BK 09/22/2025.			
Corrective Actions:		Bring into Compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12435782	1722(a) - General	California Code of Regulations - Title 14	O'Dea 8	0403714438	10/20/2025
Comment		Weeds in cellar viewed through cellar grating			
Corrective Actions:		Bring into Compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12435783	1722(a) - General	California Code of Regulations - Title 14	Rosecrans 50	0403715025	10/20/2025
Comment		Weeds on pumping jack. Reviewed by BK 09/22/2025.			
Corrective Actions:		Bring into Compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12435787	1777(a) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Rosecrans 47	0403713642	10/20/2025
Comment		Substantial amount of fluid in the cellar with fluid. Reviewed by BK 09/22/2025.			

Corrective Actions:		Bring into Compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12435780	1777(b)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Rosecrans 16	0403714667	10/20/2025
Comment		Substantial amount of fluid in the cellar with fluid. Reviewed by BK 09/22/2025.			
Corrective Actions:		Bring to Compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12435779	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Rosecrans 8	0403714999	10/20/2025
Comment		Substantial amount of fluid in the cellar with fluid. Reviewed by BK 09/22/2025.			
Corrective Actions:		Bring into Compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12435784	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	O'Dea 26W	0403723667	10/20/2025
Comment		Substantial amount of fluid in the cellar with fluid. Reviewed by BK 09/22/2025.			
Corrective Actions:		Bring into Compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12435785	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	O'Dea 18	0403714446	10/20/2025
Comment		Substantial amount of fluid in the cellar with fluid. Reviewed by BK 09/22/2025.			

Corrective Actions:		Bring into Compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12435786	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Rosecrans 17	0403714668	10/20/2025
Comment		Substantial amount of fluid in the cellar with fluid. Reviewed by BK 09/22/2025.			
Corrective Actions:		Bring to Compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12435788	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Rosecrans 11	0403714666	10/20/2025
Comment		Substantial amount of fluid in the cellar with fluid. Reviewed by BK 09/22/2025.			
Corrective Actions:		Bring into Compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12435790	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Trust 19W	0403723668	10/20/2025
Comment		Substantial amount of fluid in the cellar with fluid. Reviewed by BK 09/22/2025.			
Corrective Actions:		Bring into Compliance			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12435789	1777(d) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	O'Dea 11	0403714440	10/20/2025

Comment	Well enclosure opened and not sealed.
Corrective Actions:	Bring into Compliance



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Unresolved Violation(s)

Notice of Unresolved Violation(s)

According to the records maintained by the California Geologic Energy Management Division (CalGEM), Bridgeland Resources, LLC has been found to have not corrected the violation(s) listed below in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:	12357161			
Violation ID	Section	Code Type	Subject Name	Subject ID
12357185	1772.1(a)(1) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 8	0403714999
Compliance ID:	12372187			
Violation ID	Section	Code Type	Subject Name	Subject ID
12372253	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 8	0403714999
12372254	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 8	0403714999
Compliance ID:	12372186			
Violation ID	Section	Code Type	Subject Name	Subject ID
12372951	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 8	0403714999
12372952	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 8	0403714999
Compliance ID:	12422352			
Violation ID	Section	Code Type	Subject Name	Subject ID
12422383	1772.1.2(i) - Idle Well Engineering Analysis for 15-year Idle wells	California Code of Regulations - Title 14	Rosecrans 8	0403714999

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28

Attachment N
(Inspection Summary ID 12437805)



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspection Summary

Inspection Information					
Inspection ID	Inspection Type	Inspection Date	Inspection Name	Follow-Up Date	
12437805	Environmental Lease Inspection	10/9/2025	RJ Mejia		
Compliance Summary					
New Violation(s)		Resolved Violation(s)		Unresolved Violation(s)	
9		0		21	
Operator Information					
Operator Code		Operator Name			
11583		Bridgeland Resources, LLC			
Agent Name		Matt Sanders			
Agent Address		12720 Telegraph Road			
City	Santa Fe Springs	State	CA	Zip Code	90670
Inspected Subject(s)					
See list of Inspected Subjects on subsequent page.					
Inspection Document(s)					
No documents were uploaded during this inspection.					
New Violation(s)					
Notice of Violation According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
Compliance ID:		12437806			
See list of Violations on subsequent page.					
Unresolved Violation(s)					
Notice of Unresolved Violation(s) According to the records maintained by the California Geologic Energy Management Division (CalGEM), Bridgeland Resources, LLC has been found to have not corrected the violation(s) listed below in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
See list of Unresolved Violations on subsequent page.					



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspected Subject(s)					
Field	Lease	Subject ID	Subject Name	Subject Type	Form Name
Rosecrans	Rosecrans	0403715014	Rosecrans 35	Well	Environmental Well Site Inspection
Rosecrans	O'Dea	0403700090	O'Dea 22	Well	Environmental Well Site Inspection
Rosecrans	Rosecrans	0403714674	Rosecrans 28	Well	Environmental Well Site Inspection
Rosecrans	Rosecrans	0403715007	Rosecrans 24	Well	Environmental Well Site Inspection
Rosecrans	O'Dea	0403714431	O'Dea 2	Well	Environmental Well Site Inspection
Rosecrans	Rosecrans	0403715015	Rosecrans 36	Well	Environmental Well Site Inspection
Rosecrans	Rosecrans	0403715009	Rosecrans 29	Well	Environmental Well Site Inspection
Rosecrans	Rosecrans	0403714673	Rosecrans 26	Well	Environmental Well Site Inspection
Rosecrans	Rosecrans	0403715020	Rosecrans 41	Well	Environmental Well Site Inspection
Rosecrans	Rosecrans A	0403714656	Rosecrans A 5-A	Well	Environmental Well Site Inspection
Rosecrans	Rosecrans	0403715018	Rosecrans 39	Well	Environmental Well Site Inspection
Rosecrans	Rosecrans	0403715016	Rosecrans 37	Well	Environmental Well Site Inspection
Rosecrans	Rosecrans	0403715021	Rosecrans 42	Well	Environmental Well Site Inspection



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

New Violation(s)

Notice Of Violation

According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:

12437806

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12437808	1722(a) - General	California Code of Regulations - Title 14	O'Dea 22	0403700090	11/13/2025
Comment					
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12437810	1722(a) - General	California Code of Regulations - Title 14	Rosecrans 28	0403714674	11/13/2025
Comment		Tree Branches above well			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12437807	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Rosecrans 35	0403715014	11/13/2025
Comment		Fluid in Cellar			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12437809	1777(c)(3) - Maintenance and Monitoring of Production	California Code of Regulations - Title 14	Rosecrans 28	0403714674	11/13/2025

	Facilities, Safety Systems, and Equipment				
Comment		Fluid in the Cellar			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12437811	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Rosecrans 36	0403715015	11/13/2025
Comment		Fluid in Cellar			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12437812	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	O'Dea 2	0403714431	11/13/2025
Comment		Fluid in Cellar			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12437813	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Rosecrans 42	0403715021	11/13/2025
Comment		Bring into compliance.			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12437814	1777(c)(3) - Maintenance and Monitoring of Production	California Code of Regulations - Title 14	Rosecrans 41	0403715020	11/13/2025

	Facilities, Safety Systems, and Equipment				
Comment		Fluid in Cellar			
Corrective Actions:		Bring into compliance.			
Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12437815	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Rosecrans A 5-A	0403714656	11/13/2025
Comment		Fluid in Cellar			
Corrective Actions:		Bring into compliance.			



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Unresolved Violation(s)

Notice of Unresolved Violation(s)

According to the records maintained by the California Geologic Energy Management Division (CalGEM), Bridgeland Resources, LLC has been found to have not corrected the violation(s) listed below in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:	12309222			
Violation ID	Section	Code Type	Subject Name	Subject ID
12309537	1772.1(a)(1) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 42	0403715021
Compliance ID:	12274507			
Violation ID	Section	Code Type	Subject Name	Subject ID
12313538	1772.1(b) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 39	0403715018
12397486	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 39	0403715018
Compliance ID:	12340780			
Violation ID	Section	Code Type	Subject Name	Subject ID
12341622	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 37	0403715016
Compliance ID:	12357161			
Violation ID	Section	Code Type	Subject Name	Subject ID
12357188	1772.1(a)(1) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 26	0403714673
12357189	1772.1(a)(1) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 28	0403714674
12357190	1772.1(a)(1) - Testing of Idle Wells	California Code of Regulations - Title 14	O'Dea 22	0403700090
Compliance ID:	12320497			
Violation ID	Section	Code Type	Subject Name	Subject ID
12367338	1772.1(a)(2) - Testing of Idle Wells		O'Dea 2	0403714431
12369181	1772.1(b) - Testing of Idle Wells	California Code of Regulations - Title 14	O'Dea 2	0403714431
Compliance ID:	12372187			
Violation ID	Section	Code Type	Subject Name	Subject ID
12372249	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 26	0403714673

12372250	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 26	0403714673
12372251	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 28	0403714674
12372252	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 28	0403714674
Compliance ID:	12372186			
Violation ID	Section	Code Type	Subject Name	Subject ID
12372947	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 26	0403714673
12372948	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 26	0403714673
12372949	1772.1(a)(2) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 28	0403714674
12372950	1772.1(a)(3) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 28	0403714674
Compliance ID:	12392035			
Violation ID	Section	Code Type	Subject Name	Subject ID
12392070	1772.1(b) - Testing of Idle Wells	California Code of Regulations - Title 14	Rosecrans 37	0403715016
Compliance ID:	12422352			
Violation ID	Section	Code Type	Subject Name	Subject ID
12422377	1772.1.2(i) - Idle Well Engineering Analysis for 15-year Idle wells	California Code of Regulations - Title 14	O'Dea 22	0403700090
12422381	1772.1.2(i) - Idle Well Engineering Analysis for 15-year Idle wells	California Code of Regulations - Title 14	Rosecrans 26	0403714673
12422382	1772.1.2(i) - Idle Well Engineering Analysis for 15-year Idle wells	California Code of Regulations - Title 14	Rosecrans 28	0403714674

Attachment O

(Inspection Summary ID 12447301)

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

Inspection Summary

Inspection Information					
Inspection ID	Inspection Type	Inspection Date	Inspection Name	Follow-Up Date	
12447301	Environmental Lease Inspection	12/15/2025	Carl Jung		
Compliance Summary					
New Violation(s)		Resolved Violation(s)		Unresolved Violation(s)	
3		0		0	
Operator Information					
Operator Code		Operator Name			
11583		Bridgeland Resources, LLC			
Agent Name		Matt Sanders			
Agent Address		12720 Telegraph Road			
City	Santa Fe Springs	State	CA	Zip Code	90670
Inspected Subject(s)					
See list of Inspected Subjects on subsequent page.					
Inspection Document(s)					
No documents were uploaded during this inspection.					
New Violation(s)					
Notice of Violation According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.					
Compliance ID:		12447302			
See list of Violations on subsequent page.					



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
Sacramento, CA. 95814
T: (916) 445-5986

Inspected Subject(s)					
Field	Lease	Subject ID	Subject Name	Subject Type	Form Name
Rosecrans	Trust	0403713643	Trust 1	Well	Miscellaneous Inspection Form
Rosecrans	Trust	0403713643	Trust 1	Well	UIC Well Inspection



California
Department of Conservation
Geologic Energy Management Division

Gavin Newsom, Governor
Jennifer Lucchesi, Director

715 P Street, MS 1803
 Sacramento, CA. 95814
 T: (916) 445-5986

New Violation(s)

Notice Of Violation

According to the records maintained by the California Geologic Energy Management Division, Bridgeland Resources, LLC has been found in violation of the regulation section(s) listed in this table. Failure to correct a violation may result in enforcement action, including, but not limited to, issuance of a civil penalty or a remedial work order pursuant to Public Resources Code § 3236.5 and/or § 3224.

Compliance ID:

12447302

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12447305	1777(c)(3) - Maintenance and Monitoring of Production Facilities, Safety Systems, and Equipment	California Code of Regulations - Title 14	Trust 1	0403713643	1/14/2026

Comment

There was fluid in the cellar during the time of Inspection.
 CCR 1777(c)(3) Reviewed by BK 12/15/2025.

Corrective Actions:

Bring into compliance

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12447304	1778(a)(1) - Enclosure Specifications	California Code of Regulations - Title 14	Trust 1	0403713643	1/14/2026

Comment

The well enclosure was missing 3 strands of barbed wire during the time of Inspection.
 CCR 1778(a)(1) Reviewed by BK 12/15/2025.

Corrective Actions:

Bring into compliance

Violation ID	Section	Code Type	Subject Name	Subject ID	Remedy Due Date
12447303	1778(a)(3) - Enclosure Specifications	California Code of Regulations - Title 14	Trust 1	0403713643	1/14/2026

Comment

Corrective Actions:

Bring into Compliance

**NOTICE OF APPEAL TO THE
DIRECTOR OF THE DEPARTMENT OF CONSERVATION**

Use of this form is optional. You may use this form to prepare a Notice of Appeal from the enclosed Order. The style and content of this form are only suggestions. You may file a written notice of appeal in a different format.

Mail the completed form to the address at the bottom of this page.

Box 1: Statement of Intent to Appeal

(Review the text in this box to confirm that the operator information Order No. 1656 are accurate. Make any necessary corrections directly on the form.)

Operator, Bridgeland resources, LLC, hereby appeals from State Oil and Gas
Supervisor Order No. 1656

Box 2: Basis of Appeal

(Explain the reasons why you are appealing the order. Make your explanation as clear and complete as you can. If you need more space to write your explanation, attach additional pages. Label any attached additional pages with "Notice of Appeal re: Order No. 1656")

The reasons for this appeal are as follows:

☐ (Attach additional pages as necessary.)

Box 3: Contact Information for Operator Representative

(Provide contact information for the preferred operator representative with whom the Appeals Officer and Supervisor's legal counsel may communicate regarding the appeal.)

Name: _____

Physical Mail:

(Address) _____

(City, State, Zip) _____

Phone: (_____) _____ - _____

Email: _____

☐ I agree to document service using the email address above.

Box 4: Certification of Authority

Mail or E-mail this Notice of Appeal to the following the following address, as appropriate:

Department of Conservation, Director's Office of Appeals
715 P Street, MS 1906 (Legal Office, Chief Counsel)
Sacramento, CA 95814-3530
OfficeofAppeals@conservation.ca.gov

rev. 10/2/2024

(Verify that all information on or attached to the form is correct, then sign and date the certification where indicated.)

I am the operator named in Box 1, above, or I have authority to act on behalf of that operator for purposes of preparing and filing this Notice of Appeal.

Signature: _____

Date: _____

Printed Name: _____

Affiliation with operator: _____

(e.g., self, owner, president, legal counsel, etc.)

Mail or E-mail this Notice of Appeal to the following the following address, as appropriate:

Department of Conservation, Director's Office of Appeals
715 P Street, MS 1906 (Legal Office, Chief Counsel)
Sacramento, CA 95814-3530
OfficeofAppeals@conservation.ca.gov

rev. 10/2/2024

I declare that I am employed in the County of Sacramento, California. I am over the age of 18 and not a party to the within captioned cause. My business address is 715 P Street, MS 1803, Sacramento, California 95814. On July 17, 2026, I served the following document(s):

by enclosing them in an envelope and placing the envelope for collection and mailing by certified U.S. mail on the date and at the below listed address(es) following our ordinary business practices. I am readily familiar with this business's practice for collecting and processing correspondence for mailing. On the same day that correspondence is placed for collection and mailing, it is deposited in the ordinary course of business with the United States Postal Service in a sealed envelope with postage fully prepaid.

Matt Sanders
Bridgeland Resources, LLC
12720 Telegraph Road
Santa Fe Springs, CA 90670

Certified Mail Number: 9589 0710 5270 3983 2583 04

Shannon Kiely
Shannon Kiely

**NOTICE OF APPEAL TO THE
DIRECTOR OF THE DEPARTMENT OF CONSERVATION**

Use of this form is optional. You may use this form to prepare a Notice of Appeal from the enclosed Order. The style and content of this form are only suggestions. You may file a written notice of appeal in a different format.

Mail the completed form to the address at the bottom of this page.

Box 1: Statement of Intent to Appeal

(Review the text in this box to confirm that the operator information Order No. 1656 are accurate. Make any necessary corrections directly on the form.)

Operator, Bridgeland resources, LLC, hereby appeals from State Oil and Gas
Supervisor Order No. 1656

Box 2: Basis of Appeal

(Explain the reasons why you are appealing the order. Make your explanation as clear and complete as you can. If you need more space to write your explanation, attach additional pages. Label any attached additional pages with "Notice of Appeal re: Order No. 1656")

The reasons for this appeal are as follows:

☐ (Attach additional pages as necessary.)

Box 3: Contact Information for Operator Representative

(Provide contact information for the preferred operator representative with whom the Appeals Officer and Supervisor's legal counsel may communicate regarding the appeal.)

Name: _____

Physical Mail:

(Address) _____

(City, State, Zip) _____

Phone: (_____) _____ - _____

Email: _____

☐ I agree to document service using the email address above.

Box 4: Certification of Authority

Mail or E-mail this Notice of Appeal to the following the following address, as appropriate:

Department of Conservation, Director's Office of Appeals
715 P Street, MS 1906 (Legal Office, Chief Counsel)
Sacramento, CA 95814-3530
OfficeofAppeals@conservation.ca.gov

rev. 10/2/2024

(Verify that all information on or attached to the form is correct, then sign and date the certification where indicated.)

I am the operator named in Box 1, above, or I have authority to act on behalf of that operator for purposes of preparing and filing this Notice of Appeal.

Signature: _____

Date: _____

Printed Name: _____

Affiliation with operator: _____

(e.g., self, owner, president, legal counsel, etc.)

Mail or E-mail this Notice of Appeal to the following the following address, as appropriate:

Department of Conservation, Director's Office of Appeals
715 P Street, MS 1906 (Legal Office, Chief Counsel)
Sacramento, CA 95814-3530
OfficeofAppeals@conservation.ca.gov

rev. 10/2/2024

- 1
- 2
- 3
- 4
- 5
- 6
- 7
- 8
- 9
- 10
- 11
- 12
- 13
- 14
- 15
- 16
- 17
- 18
- 19
- 20
- 21
- 22
- 23
- 24
- 25
- 26
- 27
- 28

**ORDER TO PAY A CIVIL PENALTY AND PERFORM REMEDIAL WORK
NO. 1656**

I served the documents on the person or persons below, as follows:

Certified Mail Number:
9589 0710 5270 3983 2583 04

Shannon Kiely
Shannon Kiely