

State of California
AIR RESOURCES BOARD

EXECUTIVE ORDER D-40-38

Relating to Exemptions Under Section 27156
of the Vehicle Code

Autotronic Controls Corporation
Distributors

Pursuant to the authority vested in the Air Resources Board by Section 27156 of the Vehicle Code; and

Pursuant to the authority vested in the undersigned by Section 39515 and Section 39516 of the Health and Safety Code and Executive Order G-45-9;

IT IS ORDERED AND RESOLVED: That the installation of the Distributors manufactured and marketed by Autotronic Controls Corporation, 1490 Henry Brennan Drive, El Paso, Texas 79936 have been found not to reduce the effectiveness of the applicable vehicle pollution control system and, therefore, are exempt from the prohibitions of Section 27156 of the Vehicle Code for the following vehicle applications:

<u>Part No.</u>	<u>Device</u>	<u>Application</u>	<u>Remarks</u>
8360	Chevy Drop-In Dist.	1993 and older GM V8	Vehicles not equipped with an oxygen sensor
8361	Chevy MSD Dist.	1993 and older GM V8	Vehicles not equipped with an oxygen sensor
8365	MSD GM HEI Dist.	1993 and older GM V8	Vehicles not equipped with an oxygen sensor
8386, 8387 8388, 8389 8391	Pro-Billet Chrysler	1993 and older Chrysler V8	Vehicles not equipped with an oxygen sensor
8474	MSD Dist. Kit w/8360	1995 and older GM V8	Excluding OBD II vehicles
8515	Chevrolet Distributor	1983 and older GM inline	6 cyl. engines
8516	AMC Distributor	1993 and older AMC inline 6 cyl. engines	Vehicles not equipped with an oxygen sensors
8519	AMC Distributor	1990 and older AMC V8	Vehicles not equipped with an oxygen sensor
8523	Pro-Billet AMC	1993 and older AMC V8	Vehicles not equipped with an oxygen sensor
8528	Pro-Billet Pontiac	1993 and older Pontiac V8	Vehicles not equipped with an oxygen sensor
8529	Pro-Billet Oldsmobile	1993 and older Oldsmobile V8	Vehicles not equipped with an oxygen sensor

8552	Pro-Billet Buick	1993 and older ^{Buick} Oldsmobile V8	Vehicles not equipped with an oxygen sensor
8543	Chrysler Distributor	1975 and older Chrysler vehicles with a 331/354 cid engine	
8544	Chrysler Distributor	1975 and older Chrysler vehicles with a 392 cid engine	
8572	Tach Drive Dist.	1986 and older GM V8	Vehicles not equipped with an oxygen sensor
8595	Pro-Billet Ford FE	1986 and older Ford V8	Vehicles not equipped with an oxygen sensor

Marketing of the Distributors using any identification other than that shown in this Executive Order or marketing of the Distributors for an application other than those listed in this Executive Order shall be prohibited unless prior approval is obtained from the Air Resources Board.

Exemption of the Distributors shall not be construed as exemption to sell, offer for sale, or advertise any component of the kit as an individual device.

This Executive Order does not constitute any opinion as to the effect the use of the Distributors may have on any warranty either expressed or implied by the vehicle's manufacturer.

THIS EXECUTIVE ORDER DOES NOT CONSTITUTE A CERTIFICATION, ACCREDITATION, APPROVAL, OR ANY OTHER TYPE OF ENDORSEMENT BY THE AIR RESOURCES BOARD OF ANY CLAIMS OF THE APPLICANT CONCERNING ANTI-POLLUTION BENEFITS OR ANY ALLEGED BENEFITS OF AUTOTRONIC'S DISTRIBUTORS.

No claim of any kind, such as "Approved by the Air Resources Board", may be made with respect to the action taken herein in any advertising or other oral or written communication.

Violation of any of the above conditions shall be grounds for revocation of this order. The order may be revoked only after ten day written notice of intention to revoke the order, in which period the holder of the order may request in writing a hearing to contest the proposed revocation. If a hearing is requested, it shall be held within ten days of receipt of the request and the order may not be revoked until a determination is made after the hearing that grounds for revocation exist.

Executed at El Monte, California, this 23rd day of December 2002.


for Allen Lyons, Chief, Chief
Mobile Source Operations Division